



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Red
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-07-03
Pictures	26
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-06-23
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	16
Total items failed	4

MOT #19	2023-05-26 13:15
MOT test number	724214352251
Result	✓ Passed
Next expiry date	2024-06-23

MOT #18	2022-06-24 14:36
MOT test number	187779006418
Result	✓ Passed
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #17	2022-06-21 11:28
MOT test number	149431929684
Result	✗ Failed
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2021-06-23 15:08
MOT test number	276057958388
Result	✓ Passed



MOT #15	2020-07-28 12:05
MOT test number	231237253893
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #14	2020-07-23 07:59
MOT test number	366479141353
Result	✗ Failed
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Nearside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Front Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition downpipe /silencer (8.1.1 (a))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #13	2019-07-03 13:49
MOT test number	702844129711
Result	✓ Passed
Advice	Nearside Front c v boot has a very small cut in it but not enough to fail thhe mot

MOT #12	2018-07-17 09:25
MOT test number	698435564961
Result	✓ Passed

MOT #11	2017-07-28 16:18
MOT test number	199175751351
Result	✓ Passed
Advice	Nearside Front tyre is perished slightly
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #10**

2017-07-28 09:15

MOT test number

412047896267

Result

✗ Failed

Fail Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front tyre is perished slightly**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**MOT #9**

2016-07-18 08:43

MOT test number

893670617429

Result

✓ Passed

Advice Both rear tyres outer wall starting to crack**MOT #8**

2015-07-20 08:58

MOT test number

566206678525

Result

✓ Passed

MOT #7

2014-07-16 09:50

MOT test number

478197894157

Result

✓ Passed

MOT #6

2013-07-19 09:55

MOT test number

316390703220

Result

✓ Passed

MOT #5

2012-07-19 09:50

MOT test number

358441402490

Result

✓ Passed



MOT #4	2011-07-18 11:43
MOT test number	229809191193
Result	✓ Passed
MOT #3	2011-07-18 11:43
MOT test number	419899491176
Result	✗ Failed
<div>Pass with rectification</div> Headlamp aim too high (1.8)	
MOT #2	2010-07-21 13:04
MOT test number	640672700273
Result	✓ Passed
MOT #1	2010-03-25 15:55
MOT test number	124604480445
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-24
Last registration	2023-05-26
Complete history	See info



Registration #1	2007-03-24	12 mi
Registration #2	2010-03-25	24.312 mi
Registration #3	2010-07-21	24.318 mi
Registration #4	2011-07-18	26.505 mi
Registration #5	2012-07-19	28.767 mi
Registration #6	2013-07-19	30.734 mi
Registration #7	2014-07-16	32.677 mi
Registration #8	2015-07-20	34.266 mi
Registration #9	2016-07-18	34.337 mi
Registration #10	2017-07-28	37.438 mi
Registration #11	2018-05-29	38.557 mi
Registration #12	2019-05-29	39.557 mi
Registration #13	2020-05-29	40.557 mi
Registration #14	2021-05-29	41.557 mi
Registration #15	2022-05-29	42.557 mi
Registration #16	2023-05-29	43.557 mi
Registration #17	2024-05-29	44.557 mi
Registration #18	2025-05-29	45.557 mi
Registration #19	2026-05-29	46.557 mi
Registration #20	2027-05-29	47.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622