



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	CR-V I-DTEC SE PLUS
Colour	Brown
Year of manufacture	2016
Top speed	113 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 3


Date	2021-07-10
Pictures	20
Listing price	View report



source: [heycar.co.uk](https://www.heycar.co.uk)

Entry 2

Date	2021-07-09
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-06-23
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-13
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #7 2023-09-08 11:51

MOT test number 267626887583

Result ✓ Passed

Next expiry date 2024-09-13

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2023-08-31 14:13

MOT test number 301776954525

Result ✗ Failed**MAJOR** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2022-09-14 07:43

MOT test number 991845914972

Result ✓ Passed

**MOT #4** 2022-09-12 12:13**MOT test number** 355886356508**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #3** 2021-07-26 13:21**MOT test number** 597788107448**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2020-09-12 10:52**MOT test number** 186783824003**Result** ✓ Passed**MOT #1** 2019-09-27 12:24**MOT test number** 776658999622**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
13 September 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 SK66RWJ
Plate since	2019-03-29
Current registration	 SK66RWJ
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-30
Last registration	2023-09-08
Complete history	See info



Registration #1	2016-09-30	6 mi
Registration #2	2019-09-27	29.265 mi
Registration #3	2020-09-12	39.671 mi
Registration #4	2020-09-12	39.671 mi
Registration #5	2020-09-12	39.671 mi
Registration #6	2020-09-12	39.671 mi
Registration #7	2020-09-12	39.671 mi
Registration #8	2020-09-12	39.671 mi
Registration #9	2020-09-12	39.671 mi
Registration #10	2020-09-12	39.671 mi
Registration #11	2020-09-12	39.671 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1592 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A23005794