



General information

| | |
|---------------------|------------------------|
| Make | VOLKSWAGEN |
| Model | SHARAN SE TDI (115BHP) |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 112 mph |
| 0 - 60 mph | 13.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 115 BHP |
| Max. torque | 310 Nm at 1.900 rpm |
| Engine capacity | 1.896 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 172 g/km |
| CO2 label | H |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-08-07 |
| Pictures | 13 |
| Listing price | View report |



source: autotrader.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-30 |
| Pictures | 11 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-20 |
| MOT pass rate | 70 % |
| MOT passed | 14 |
| Failed MOT tests | 6 |
| Total advice items | 48 |
| Total items failed | 8 |

| | |
|------------------|------------------|
| MOT #20 | 2023-08-21 13:51 |
| MOT test number | 443391881120 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-20 |

| | |
|-------------------------|--|
| MOT #19 | 2023-08-21 13:51 |
| MOT test number | 764904267221 |
| Result | ✗ Failed |
| Pass with rectification | Front Registration plate inscription illegible (0.1 (b)) |
| Pass with rectification | Offside Side repeater not working (4.4.1 (a) (ii)) |



MOT #18

2023-08-02 10:54

MOT test number

448416226474

Result

✗ Failed

- MAJOR Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice Rear suspension components corroded
- MAJOR Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner cill (5.3.6 (a) (i))
- Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice Rear Outer Tyre slightly damaged/cracking or perishing Tyres cracking (5.2.3 (d) (ii))
- MAJOR Nearside Rear Seat belt buckle missing (7.1.2 (d))
- Advice Undertrays fitted not allowing full inspection
- MAJOR Offside Front Side repeater not working (4.4.1 (a) (ii))
- Advice Front subframe bushes slightly worn but not excessively
- Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Inner cill (5.3.6 (a) (i))
- Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #17**

2022-08-01 09:02

MOT test number

800852927724

Result

✓ Passed

- Advice** Different road wheels on front axle
- Advice** Nearside Front Tyre slightly damaged On outer sidewall (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald on edges (5.2.3 (e))

MOT #16

2021-07-16 13:06

MOT test number

112206555425

Result

✓ Passed

- Advice** Central Front veh reg plate cracked
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #15

2021-07-15 10:03

MOT test number

312704863026

Result

✗ Failed

- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Nearside Front Lower Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting 1 of 2 holes (6.2.2 (d) (i))
- MAJOR** Offside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Nearside Front Lower Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting 2 of 2 holes (6.2.2 (d) (i))
- Advice** Central Front veh reg plate cracked

**MOT #14** 2020-07-20 09:18**MOT test number** 409265720113**Result** ✓ Passed**Advice** Front number plate cracked**Advice** Brake pad warning light on, all brake are good**MOT #13** 2020-07-20 09:18**MOT test number** 751078274968**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Front number plate cracked**Advice** Brake pad warning light on, all brake are good**MOT #12** 2019-07-27 15:43**MOT test number** 205954032035**Result** ✓ Passed**MOT #11** 2018-07-10 16:46**MOT test number** 286049360493**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear tyres are cracking**MOT #10** 2017-07-29 15:43**MOT test number** 670564394666**Result** ✓ Passed

**MOT #9** 2016-07-12 14:06**MOT test number** 836471941920**Result** ✓ Passed**Advice** Offside rear tyre worn uneven - 215/55 16**Advice** Central lock fault / doors have to be unlock from inside of the car**MOT #8** 2015-07-13 13:24**MOT test number** 538944995158**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-05-15 11:59**MOT test number** 648455534147**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-05-15 11:59**MOT test number** 417525334150**Result** ✗ Failed**Pass with rectification** Nearside Front Stop lamp not working (1.2.1b)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-05-17 09:10**MOT test number** 657257633172**Result** ✓ Passed**Notice** Nail in nearside front tyre inner edge**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #4** 2012-07-05 12:35**MOT test number** 386237482157**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2011-07-08 15:07**MOT test number** 848239281188**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-07-08 15:07**MOT test number** 265259681484**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**MOT #1** 2010-07-09 12:43**MOT test number** 442720690129**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 20 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 7 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |
| Current registration |  ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2007-07-11 |
| Last registration | 2023-08-21 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-07-11 | 26 mi |
| Registration #2 | 2010-07-09 | 39.999 mi |
| Registration #3 | 2011-07-08 | 53.616 mi |
| Registration #4 | 2012-07-05 | 61.739 mi |
| Registration #5 | 2013-05-17 | 69.025 mi |
| Registration #6 | 2014-05-15 | 72.420 mi |
| Registration #7 | 2015-07-13 | 75.726 mi |
| Registration #8 | 2016-07-12 | 79.699 mi |
| Registration #9 | 2017-07-29 | 82.700 mi |
| Registration #10 | 2018-07-10 | 85.241 mi |
| Registration #11 | 2019-07-27 | 88.198 mi |
| Registration #12 | 2020-08-01 | 91.217 mi |
| Registration #13 | 2021-08-01 | 94.236 mi |
| Registration #14 | 2022-08-01 | 97.255 mi |
| Registration #15 | 2023-08-01 | 100.274 mi |
| Registration #16 | 2024-08-01 | 103.293 mi |
| Registration #17 | 2025-08-01 | 106.312 mi |
| Registration #18 | 2026-08-01 | 109.331 mi |
| Registration #19 | 2027-08-01 | 112.350 mi |
| Registration #20 | 2028-08-01 | 115.369 mi |
| Registration #21 | 2029-08-01 | 118.388 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1730 mm |
| Length | 4634 mm |
| Wheel base | 2841 mm |
| Kerb weight | 1928 kg |
| Max. allowed weight | 2510 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|------------------------|------------|
| Number of seats | 7 |
| Engine number | BVK 021905 |