





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Black
Year of manufacture	2011
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #13		2024-04-10 14:34
MOT test	number	436244581861
Result		✓ Passed
Next expi	ry date	2025-04-09
Advice	Bonnet corroded.	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #12	2024-04-04 10:26
MOT test number	638454394170
Result	X Failed
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice Bonnet corroded.	
Advice Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Front Direction indicator adversely affected by the operation of and	other lamp (4.4.3 (b))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11		2023-03-20 14:22
MOT test	number	290198287578
Result		✓ Passed
Advice	Front number plate cracked and slightly loose	
Advice	All direction indicators slightly discoloured (4.4.3 (a))	
Advice	Rear outer brake pads visually wearing slightly low? can't fully see, discs du	ull/slightly worn
Advice	Rear Child Seat fitted not allowing full inspection of adult belt 2 x child seat	s in rear
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Steering and suspension components slightly corroded	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #10	2022-04-07 15:15
MOT test number	825068859861
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #9	2021-04-09 14:47
MOT test number	181291487531
Result	✓ Passed
MOT #8	2021-04-08 07:51
MOT test number	294749844580
Result	X Failed
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	

MOT #7	2020-07-29 14:01
MOT test number	502600718443
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6		2019-08-08 13:54
MOT test	number	695858776935
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Engine covers and under trays fitted not allowing for full inspection of vehicle	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #5	2018-08-22 10:08
MOT test	number 118142411979
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened inside face (1.1.14 (a)
Advice (a) (ii))	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inside face (1.1.14

MOT #4	2017-08-08 15:53
MOT test number	387234553284
Result	✓ Passed
MOT #3	2016-08-09 15:37
MOT test number	877244945684
Result	✓ Passed
MOT #2	2015-07-14 15:25

MOT #2	2015-07-14 15:25
MOT test number	318865395172
Result	✓ Passed
Notice Nail in nearside front tyre	

MOT #1	2014-07-30 16:36
MOT test number	828181014245
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

NG11GCX

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYU have? Check it in the premium report and see all owner registrations. Download the full report here .	JNDAI
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

THE PERSON NAMED IN COLUMN TO THE PE	

Plate changes

See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	mm-n-m
Current registration	UK ZIS
Mode sizes	

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-08
Last registration	2024-04-10
Complete history	See info



Registration #1	2011-07-08	16 mi
Registration #2	2014-07-30	25.816 mi
Registration #3	2015-07-14	29.805 mi
Registration #4	2016-08-09	36.211 mi
Registration #5	2017-08-08	41.420 mi
Registration #6	2018-08-22	42.896 mi
Registration #7	2019-08-08	52.839 mi
Registration #8	2020-07-29	57.940 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air condition
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 12/12

Number of axles 2

Engine number D4FDBZ035628