



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2022-10-21
Pictures	14
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-18
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	18
Total items failed	7

MOT #17	2024-02-28 15:13
MOT test number	525819976736
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Nearside and Offside, rearmost bush (5.3.4 (a) (i))

MOT #16	2022-10-27 16:04
MOT test number	473648544863
Result	✓ Passed
Advice	Rear brake discs have corrosion, but performance not affected.

MOT #15	2022-05-30 15:21
MOT test number	351652789170
Result	✓ Passed

MOT #14	2021-06-19 11:04
MOT test number	754667162608
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-07-21 15:02**MOT test number** 397395847094**Result** ✓ Passed

- Minor** Nearside Front Side repeater insecure (4.4.1 (c) (i))
- Minor** Offside Front Side repeater insecure (4.4.1 (c) (i))
- Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))

MOT #12 2020-07-21 08:43**MOT test number** 537810800165**Result** ✗ Failed

- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))
- Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))
- Minor** Nearside Front Side repeater insecure (4.4.1 (c) (i))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Offside Front Side repeater insecure (4.4.1 (c) (i))

MOT #11 2019-07-23 08:33**MOT test number** 376231452399**Result** ✓ Passed**MOT #10** 2018-07-03 12:09**MOT test number** 865652587532**Result** ✓ Passed

**MOT #9** 2018-07-03 08:21**MOT test number** 649974994711**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2017-07-22 09:32**MOT test number** 684709922333**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2016-06-25 09:55**MOT test number** 722048620410**Result** ✓ Passed**MOT #6** 2015-07-23 16:48**MOT test number** 576944905274**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2015-07-23 13:42**MOT test number** 947264405289**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2014-06-07 12:17**MOT test number** 836928754129**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2013-07-03 15:15**MOT test number** 998144583171**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2013-07-03 15:15**MOT test number** 515294283164**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #1** 2012-06-21 15:59**MOT test number** 218673472154**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-07-06
Last registration	2024-02-28
Complete history	See info



Registration #1	2009-07-06	28 mi
Registration #2	2012-06-21	44.151 mi
Registration #3	2013-07-03	49.239 mi
Registration #4	2014-06-07	53.922 mi
Registration #5	2015-07-23	60.123 mi
Registration #6	2015-07-23	60.123 mi
Registration #7	2016-06-25	64.290 mi
Registration #8	2017-07-22	68.707 mi
Registration #9	2018-07-03	74.346 mi
Registration #10	2018-07-03	74.346 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi
Registration #18	2019-06-20	75.377 mi
Registration #19	2019-06-20	75.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607