



Mercedes-Benz




report date: 2024-09-18

General information

Make	MERCEDES-BENZ
Model	VITO 116CDI TOURER SELECT AUTO 114CDI TOURER SELECT L3
Colour	Silver
Year of manufacture	2020
Top speed	114 mph
Gearbox	9 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	330 Nm at 1.250 rpm
Engine capacity	1.950 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	38.2 mpg
CO2 emission	193 g/km
CO2 label	J







Internet history

Entry 1

Date	2024-06-12
Pictures	2
Listing price	View report

This dealer has committed to

- Provide a minimum of 6 months MOT on all vehicles
- Make you to test drive any vehicle
- Welcome any vehicle inspection before you buy
- Provide you every vehicle in its presentation
- Provide 12 months and service records where available
- Work closely with you and the AA Car team to help with any issues

Now that's reass 



source: cargurus.co.uk



MOT history

MOT expiry date	2025-09-30
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #6 2024-10-01 16:05

MOT test number 743042504632

Result ✔ Passed

Next expiry date 2025-09-30

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))
- Advice** Rear Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2024-10-01 13:15

MOT test number 756799076226

Result ✘ Failed

- Advice** Rear Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))
- Fail** Brake pedal has insufficient reserve travel parking brake (1.1.2 (a))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Minor** Parking brake lever ratchet mechanism obviously worn (1.1.6 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))



MOT #4 2024-09-18 12:24

MOT test number 662309813927

Result ✔ Passed

MOT #3 2024-09-18 12:24

MOT test number 153003387075

Result ✘ Failed

Pass with rectification Brake pedal has insufficient reserve travel parking brake (1.1.2 (a))

MOT #2 2023-08-24 10:08

MOT test number 615904357295

Result ✔ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2023-08-24 08:45

MOT test number 832579972167

Result ✘ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 September 2025

✓
MOT

Expires:
30 September 2025

Tax status	Valid until 1 September
Days left	328
MOT expiry date	30 September 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
First licence fee (12 months)	£ 1.565,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 2.220,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-09-18
Current registration	XXXXX
Plate since	2024-09-18

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2020-07-30
Last registration	2024-10-01
Complete history	See info



Registration #1	2020-07-30	18 mi
Registration #2	2023-08-24	32.036 mi
Registration #3	2023-08-24	32.036 mi
Registration #4	2023-08-24	32.036 mi
Registration #5	2023-08-24	32.036 mi
Registration #6	2023-08-24	32.036 mi
Registration #7	2023-08-24	32.036 mi
Registration #8	2023-08-24	32.036 mi

[More info >](#)



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1917 mm
Length	5370 mm
Max. allowed weight	3200 kg

Additional information

Number of seats	9
Number of axles	2
Engine number	65492080719555