




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Grey
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-04-30
Pictures	24
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-04-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #13	2024-04-16 11:53
MOT test number	523104251216
Result	✓ Passed
Next expiry date	2025-04-15

MOT #12	2023-04-14 09:00
MOT test number	926973897349
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened Front and rear discs slightly scored (1.1.14 (a) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened Slightly corroded (5.3.3 (b) (i))

MOT #11	2022-03-01 10:20
MOT test number	844555935231
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-03-01 16:00
MOT test number	516519617476
Result	✓ Passed

**MOT #9** 2021-03-01 09:17**MOT test number** 930404342142**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2020-03-02 11:07**MOT test number** 713298986043**Result** ✓ Passed**Advice** Parts of rear suspension components corroded**MOT #7** 2019-03-04 11:42**MOT test number** 613657318396**Result** ✓ Passed**MOT #6** 2019-03-01 14:36**MOT test number** 124959785297**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Shock absorbers damaged to the extent that it does not function (5.3.2 (b))**MOT #5** 2018-03-09 11:12**MOT test number** 974034371260**Result** ✓ Passed

**MOT #4** 2017-03-01 11:02**MOT test number** 780441690162**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-03-19 09:38**MOT test number** 134953570645**Result** ✓ Passed**Advice** Both rear tyres worn on inner edge.**Advice** Offside Rear Tyre worn close to the legal limit 2.3mm (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2015-03-14 09:23**MOT test number** 116843575493**Result** ✓ Passed**MOT #1** 2014-03-15 09:16**MOT test number** 487754874008**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
15 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	368
<b>MOT expiry date</b>	15 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-28
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2011-03-28	20 mi
Registration #2	2014-03-15	32.175 mi
Registration #3	2015-03-14	44.055 mi
Registration #4	2016-03-19	55.834 mi
Registration #5	2017-03-01	63.966 mi
Registration #6	2018-03-09	72.278 mi
Registration #7	2019-03-01	80.861 mi
Registration #8	2019-03-04	80.902 mi
Registration #9	2020-03-29	80.902 mi
Registration #10	2020-03-29	80.902 mi
Registration #11	2020-03-29	80.902 mi
Registration #12	2020-03-29	80.902 mi
Registration #13	2020-03-29	80.902 mi
Registration #14	2020-03-29	80.902 mi
Registration #15	2020-03-29	80.902 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAY 586764