



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D3 SE LUX SOLSTICE
Colour	Black
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-06
Pictures	9
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #7	2020-09-16 15:07
MOT test number	402435721798
Result	✓ Passed
Next expiry date	2021-09-27
Advice Rear Registration plate deteriorated but not likely to be misread ADVISE TO CHANGE SOON AS POSSIBLE (0.1 (b))	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords On outer side wall (5.2.3 (d) (i))	

MOT #6	2019-09-25 08:22
MOT test number	912324407956
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Rear Registration plate deteriorated	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2018-09-10 14:44
MOT test number	252723441761
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

**MOT #4** 2018-09-10 10:22**MOT test number** 106028967478**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2017-09-28 14:00**MOT test number** 481847448440**Result** ✓ Passed**MOT #2** 2017-02-06 16:46**MOT test number** 890006682506**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #1** 2016-02-10 11:58**MOT test number** 753001483353**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LK13LMJ
Plate since	2024-03-29
Current registration	LK13LMJ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2013-03-01
Last registration	2020-09-16
Complete history	See info



Registration #1	2013-03-01	11 mi
Registration #2	2016-02-10	15.193 mi
Registration #3	2017-02-06	25.268 mi
Registration #4	2017-09-28	25.859 mi
Registration #5	2018-09-10	34.468 mi
Registration #6	2019-09-10	35.277 mi
Registration #7	2019-09-10	35.277 mi
Registration #8	2019-09-10	35.277 mi
Registration #9	2020-09-16	35.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	2025 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1811 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	1224080
---------------	---------