



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI ECOFLEX S/S
Colour	Red
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1	
Date	2021-09-09
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #9	2023-09-06 13:37
MOT test number	394694739239
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Nearside Rear Nail in tyre
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Nearside Rear brake beginning to stick on

MOT #8	2022-09-08 12:32
MOT test number	747396552723
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2022-09-08 11:07**MOT test number** 160279428144**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge 2nd layer rubber. 225/45 17 (5.2.3 (e))**DANGEROUS** Nearside Front Inner Tyre has ply or cords exposed 225/45 17 (5.2.3 (d) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #6** 2021-09-07 15:48**MOT test number** 712335282003**Result** ✓ Passed**MOT #5** 2021-08-04 09:40**MOT test number** 241704571027**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2020-08-03 14:55**MOT test number** 902176026050**Result** ✓ Passed**MOT #3** 2019-05-02 09:02**MOT test number** 988453183766**Result** ✓ Passed



MOT #2	2018-05-03 14:42
MOT test number	827397064615
Result	✓ Passed

MOT #1	2017-04-29 11:05
MOT test number	834332446328
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
7 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	7 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>DF14TKE</b>
Plate since	2019-03-29
Current registration	 <b>DF14TKE</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-07
Last registration	2023-09-06
Complete history	<a href="#">See info</a>



Registration #1	2014-07-07	10 mi
Registration #2	2017-04-29	18.762 mi
Registration #3	2018-05-03	21.709 mi
Registration #4	2019-05-02	23.682 mi
Registration #5	2020-08-03	25.879 mi
Registration #6	2021-08-04	27.112 mi
Registration #7	2023-09-06	28.355 mi
Registration #8	2023-09-06	28.355 mi
Registration #9	2023-09-06	28.355 mi
Registration #10	2023-09-06	28.355 mi
Registration #11	2023-09-06	28.355 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A1141184FWXX0075LVL