





report date: 2024-03-28

General information

Make	KIA
Model	OPTIMA CRDI 3 ISG
Colour	Black
Year of manufacture	2018
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/10



Internet history

Entr	. 1
EIIU	vт

Lifety 1	
Date	2021-08-06
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2025-04-29
	2023 0 . 23
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	4
Total items failed	0

MOT #4		2024-04-23 15:31
MOT test	number	681875899173
Result		✓ Passed
Next expi	ry date	2025-04-29
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3		2023-04-27 11:01
MOT test	number	173402518179
Result		✓ Passed
Advice adjustmen	Service brake requirements only just met. It would appear that the braking of or repair (1.2.1 (c)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	g system requires

MOT #2	2022-04-29 09:51
MOT test number	945976100687
Result	✓ Passed
MOT #1	2021-04-09 08:46
MOT test number	703374533177
Result	✓ Passed

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More Info > Plate changes See in this check if this KIA had different number plates.		
Plate changes See in this check if this KIA had different number plates.		
Plate changes See in this check if this KIA had different number plates.		
Plate changes See in this check if this KIA had different number plates.	HARMAN CO. C.	
Plate changes See in this check if this KIA had different number plates.		
Plate changes See in this check if this KIA had different number plates.	***************************************	
Plate changes See in this check if this KIA had different number plates.		
Plate changes See in this check if this KIA had different number plates.	THE PARTY OF THE P	
Plate changes See in this check if this KIA had different number plates.	***************************************	
Plate changes See in this check if this KIA had different number plates.	***************************************	
Plate changes See in this check if this KIA had different number plates.		
See in this check if this KIA had different number plates.		More info >
See in this check if this KIA had different number plates.		
狀 UK	Plate changes	
狀 UK		
NE VIK	See in this check if this kid had different number plates.	
NE VIK		
NE VIK	Number of plates	,
NE VIK		
Platte since	Current registration	IK SIE
Platte since	Plate since	
Platte since		
More info	Current registration	NIZ AIS UK
More info	Finite since	
More info		
		More info >

CarCheck.co.uk page 7/10



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-04-30
Last registration	2024-04-23
Complete history	See info



Registration #1	2018-04-30	29 mi
Registration #2	2021-04-09	31.060 mi
Registration #3		D.777 es
Registration #4		71.777 es
Registration #5		11.777 es
Registration #6		11.777 es

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	86%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1470 mm
Length	4855 mm
Wheel base	2805 mm
Kerb weight	1750 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/

Number of axles 2

Engine number D4FDHH209643