





report date: 2024-03-29

General information

Make	MINI
Model	COOPER
Colour	Grey
Year of manufacture	2017
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-02-02	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-12-09
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	21
Total items failed	0

MOT #6		2023-12-07 14:49
MOT test	number	581782559710
Result		✓ Passed
Next exp	iry date	2024-12-09
Minor by an obs	Offside Lower Driver's view to the front outside the swept area of the windscreen $(3.1 (a) (i))$	en wipers restricted
Advice	Nearside Front tyre damaged around outer sidewall	
Advice	Offside Front wheel-rim damaged	
Advice	Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front wheel-rim badly damaged	
Advice	Offside Front tyre badly damaged on outer sidewall close to cord construction	
Advice	Engine cover and undertrays fitted obscuring view of testable items	
Advice	Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5		2022-12-02 12:27
MOT test	number	884528227169
Result		✓ Passed
Advice	Nearside Front wheel-rim badly damaged	
Advice	Front brake discs worn and lipped	
Advice	Engine cover and undertrays fitted obscuring view of testable items	
Advice	Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front tyre slightly damaged on outer sidewall	

MOT #4		2021-12-10 14:48
MOT test	number	975464120611
Result		✓ Passed
Advice	Offside Front tyre badly damaged on outer sidewall	
Advice	Offside Rear tyre going out of shape on inner edge	
Advice	Engine cover and undertrays fitted obscuring view of testable items	
Advice	Nearside Front wheel-rim badly damaged	
Advice	Offside Front wheel-rim damaged	
Advice	Front brake discs worn and lipped	

MOT #3	2020-12-10 10:10
MOT test number	550886667968
Result	✓ Passed
MOT #2	2020-05-30 10:17
MOT test number	692084145382
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1

MOT test number

Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 5/12



report date: 2024-03-29

Expired at 17 April 2024

Tax & MOT check





Tax expired: 17 April 2024

Expires:
9 December 2024

Days left 13 days too late

MOT expiry date 9 December 2024

Full MOT history See MOT history

Tax calculation

Tax status

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
manage of the same	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of cities	
Mumber of preten	
Current registration	NE UK
Flate since	m-o-o
Format matcheding	NE
	UK UK
Plate since	
	More info >
	More into >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



SE17BWG
report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-05-30
Last registration	2023-12-07
Complete history	See info



Registration #1	2017-05-30	6 mi
Registration #2	2020-05-30	24.161 mi
Registration #3	2020-12-10	29.968 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1190 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page 1	12/12

Number of axles2Engine number33455030