




report date: 2024-03-28

General information

Make	VOLVO
Model	C70 C70 LPT CONV GT
Colour	Black
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	229 Nm at 1.800 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	19.6 mpg
Consumption extra urban	36.7 mpg
Consumption combined	28.0 mpg





Internet history

Entry 1

Date	2021-08-06
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #21	2023-04-27 07:34
MOT test number	381732687508
Result	✓ Passed
Next expiry date	2024-04-26
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2022-04-27 15:00
MOT test number	333991365028
Result	✓ Passed

MOT #19	2022-04-27 15:00
MOT test number	156470586556
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #18	2021-03-04 14:19
MOT test number	129589070717
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge also sidewall damage (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #17 2021-02-25 11:44

MOT test number 144533621456

Result ✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge also sidewall damage (5.2.3 (e))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Offside Side repeater incorrect colour (4.4.3 (a))

MOT #16 2020-03-04 15:45

MOT test number 589364493346

Result ✓ Passed

Advice Coolant leak

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #15 2020-03-04 15:45

MOT test number 795553516950

Result ✗ Failed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Advice** Coolant leak
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2018-09-14 08:15

MOT test number 421820854585

Result ✓ Passed

MOT #13 2018-08-31 14:36

MOT test number 761836127391

Result ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #12 2017-09-11 10:39

MOT test number 444764795741

Result ✓ Passed

- Advice** Offside Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #11 2016-09-12 16:42

MOT test number 500297333453

Result ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #10 2015-09-17 14:50

MOT test number 475193402830

Result ✓ Passed

MOT #9 2014-09-30 14:14

MOT test number 438403674278

Result ✓ Passed

MOT #8 2013-09-16 09:30

MOT test number 866169953225

Result ✓ Passed

MOT #7 2012-09-17 10:32

MOT test number 365161062220

Result ✓ Passed

MOT #6 2012-09-17 10:32

MOT test number 909711862221

Result ✗ Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

MOT #5 2011-09-09 15:35

MOT test number 198042151245

Result ✓ Passed

Notice Nearside rear tyre deteriorating



MOT #4 2011-09-09 15:35

MOT test number 855182651285

Result ✗ Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Nearside rear tyre deteriorating

MOT #3 2010-09-20 12:27

MOT test number 774583660239

Result ✓ Passed

Notice Off side front tyre wearing on edges

Notice Near side rear tyre deteriorating in treads

MOT #2 2009-09-18 13:13

MOT test number 311761469480

Result ✓ Passed

Notice Near side rear tyre deteriorating

MOT #1 2008-09-03 10:13

MOT test number 601957948234

Result ✓ Passed




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LK550EX
Plate since	2024-03-28
Current registration	LK550EX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-24
Last registration	2023-04-27
Complete history	See info



Registration #1	2005-09-24	12 mi
Registration #2	2008-09-03	24.106 mi
Registration #3	2009-09-18	31.479 mi
Registration #4	2010-09-20	36.547 mi
Registration #5	2011-09-09	41.245 mi
Registration #6	2012-09-17	45.235 mi
Registration #7	2013-09-16	49.293 mi
Registration #8	2014-09-30	55.219 mi
Registration #9	2015-09-17	58.383 mi
Registration #10	2016-09-12	60.829 mi
Registration #11	2017-09-11	62.798 mi
Registration #12	2018-09-03	65.219 mi
Registration #13	2019-09-18	68.383 mi
Registration #14	2020-09-20	71.245 mi
Registration #15	2021-09-09	74.106 mi
Registration #16	2022-09-17	77.235 mi
Registration #17	2023-04-27	80.547 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	2660 mm
Length	4720 mm
Wheel base	1420 mm
Kerb weight	1565 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	3478346