



NX07HHE

report date: 2024-03-28

General information

| | |
|---------------------|--------|
| Make | FIAT |
| Model | DUCATO |
| Colour | Silver |
| Year of manufacture | 2007 |
| Gearbox | - |

Engine & fuel consumption

| | |
|-----------------|----------|
| Engine capacity | 2.200 cc |
| Fuel type | Diesel |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-07 |
| Pictures | 8 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-09 |
| MOT pass rate | 54 % |
| MOT passed | 14 |
| Failed MOT tests | 12 |
| Total advice items | 60 |
| Total items failed | 20 |

| | |
|------------------|--|
| MOT #26 | 2024-02-06 11:23 |
| MOT test number | 201709873489 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-09 |
| Minor | Windscreen wiper blade defective (3.4 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #25 | 2023-02-10 10:56 |
| MOT test number | 731538928442 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #24 | 2023-01-24 09:52 |
| MOT test number | 163794547873 |
| Result | ✗ Failed |
| Advice | Front Suspension arm pin or bush worn but not resulting in excessive movement both front rear wish bone bushes (5.3.4 (a) (i)) |
| MAJOR | Front Exhaust has a major leak of exhaust gases split at cat (6.1.2 (a)) |
| Advice | Front Power steering pipe/hose has slight seepage (2.1.5 (a)) |
| DANGEROUS | Nearside Rear Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected outer sill hold (5.3.6 (a) (ii)) |

**MOT #23**

2022-01-19 15:02

MOT test number

449580463535

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Tyre slightly damaged/cracking or perishing both rear tyres (5.2.3 (d) (ii))
- Advice** Rear Leaf spring has slight wear in an anchor pin and/or bush spring eye bushes (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #22

2022-01-17 12:25

MOT test number

172966056170

Result

✗ Failed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Leaf spring has slight wear in an anchor pin and/or bush spring eye bushes (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- MAJOR** Offside Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- MAJOR** Nearside Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Tyre slightly damaged/cracking or perishing both rear tyres (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))



MOT #21 2021-01-25 11:32

MOT test number 695132579768

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #20 2021-01-22 16:16

MOT test number 160237643336

Result ✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #19 2019-06-27 11:51

MOT test number 367535519721

Result ✓ Passed

Advice Underside of vehicle heavily coated with underseal

Advice Offside Front Play in steering rack inner joint(s)

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #18**

2019-06-22 13:08

MOT test number

277642533287

Result**✗ Failed**

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Underside of vehicle heavily coated with underseal
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #17

2018-05-02 08:16

MOT test number

839642280455

Result**✓ Passed**

- Advice** Corrosion nearside rear inner sill although not considered excessive
- Advice** Parking brake efficiency only just met it would appear adjustment or repair is required
- Advice** Corrosion offside rear inner sill although not considered excessive

MOT #16

2017-04-22 10:18

MOT test number

843210962241

Result**✓ Passed****MOT #15**

2017-04-20 11:52

MOT test number

133013037377

Result**✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Exhaust system not adequately supported rear silencer (7.1.1)

**MOT #14**

2016-04-22 14:54

MOT test number

832664142446

Result

✓ Passed

Advice O/S INNER STEERING RACK JOINT SOME MOVMENT**Advice** HAND BRAKE ON MINIMUM EFFORT**MOT #13**

2016-04-13 16:05

MOT test number

739366953803

Result

✗ Failed

Fail Offside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Advice** O/S INNER STEERING RACK JOINT SOME MOVMENT**Fail** Nearside Front Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** HAND BRAKE ON MINIMUM EFFORT**Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #12**

2015-04-16 14:47

MOT test number

456466805196

Result

✓ Passed

Notice Rear brake discs corroded**Notice** Front brake pads wearing thin**Notice** O/s/f play at steering inner track rod**Notice** Front brake discs corroded

**MOT #11** 2015-04-16 09:37**MOT test number** 289936505199**Result** ✗ Failed**Notice** O/s/f play at steering inner track rod**Notice** Front brake discs corroded**Fail** Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Rear brake discs corroded**Notice** Front brake pads wearing thin**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #10** 2014-06-04 11:56**MOT test number** 996785054139**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2014-06-03 10:42**MOT test number** 219484954402**Result** ✗ Failed**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Front wheel bearing has excessive play (2.5.A.3c)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside front brake binding (3.7.B.1)

**MOT #8** 2013-05-30 15:07**MOT test number** 258080053119**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #7** 2013-05-30 09:36**MOT test number** 296950053184**Result** ✗ Failed**Fail** Offside Lower Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Play in steering rack inner joint(s)**MOT #6** 2012-06-25 15:06**MOT test number** 548467772181**Result** ✓ Passed**Notice** Corrosion starting to affect the exhaust**Notice** Play in the steering rack at the o/s**MOT #5** 2012-06-22 13:00**MOT test number** 179744072160**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Corrosion starting to affect the exhaust**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Play in the steering rack at the o/s**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #4** 2012-06-13 12:07**MOT test number** 505895662165**Result** ✗ Failed**Fail** Nearside Bonded suspension unit bonding failed and part of unit is likely to become displaced (2.4.F.2)**Fail** Offside Front Ball joint has excessive play (2.2.B.1f)**Pass with rectification** Offside Headlamp aim too far to the left (1.8)**Fail** Offside Bonded suspension unit bonding failed and part of unit is likely to become displaced (2.4.F.2)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #3** 2011-06-06 12:49**MOT test number** 979447151197**Result** ✓ Passed**MOT #2** 2010-06-22 12:46**MOT test number** 983473070126**Result** ✓ Passed**MOT #1** 2010-06-18 11:41**MOT test number** 844489860188**Result** ✗ Failed**Fail** Mechanical brake component has restricted free movement (3.5.1k)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 9 February 2025 |
| Full MOT history | See MOT history |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|--------------|--------|
| XXXXXX | XXXXXX |
| XXXXXXXXXXXX | XXXXXX |
| XXXXXXXXXX | XXXXXX |
| XXXXXX | XXXXXX |
| XXXXXXXXXXXX | XXXXXX |
| XXXXXXXXXX | XXXXXX |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXX |
| Plate since | 2019-09-29 |
| Current registration |  XXXXX |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 28 |
| First mileage registration | 2007-06-23 |
| Last registration | 2024-02-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-06-23 | 14 mi |
| Registration #2 | 2010-06-18 | 26.444 mi |
| Registration #3 | 2010-06-22 | 26.479 mi |
| Registration #4 | 2011-06-06 | 32.127 mi |
| Registration #5 | 2012-06-13 | 39.701 mi |
| Registration #6 | 2012-06-22 | 40.142 mi |
| Registration #7 | 2012-06-25 | 40.142 mi |
| Registration #8 | 2013-05-30 | 48.923 mi |
| Registration #9 | 2013-05-30 | 48.923 mi |
| Registration #10 | 2014-06-03 | 56.752 mi |
| Registration #11 | 2014-06-04 | 56.752 mi |
| Registration #12 | 2015-04-16 | 60.940 mi |
| Registration #13 | 2015-04-16 | 60.940 mi |
| Registration #14 | 2016-04-13 | 73.667 mi |
| Registration #15 | 2016-05-20 | 75.277 mi |
| Registration #16 | 2016-05-20 | 75.277 mi |
| Registration #17 | 2016-05-20 | 75.277 mi |
| Registration #18 | 2016-05-20 | 75.277 mi |
| Registration #19 | 2016-05-20 | 75.277 mi |
| Registration #20 | 2016-05-20 | 75.277 mi |
| Registration #21 | 2016-05-20 | 75.277 mi |
| Registration #22 | 2016-05-20 | 75.277 mi |
| Registration #23 | 2016-05-20 | 75.277 mi |
| Registration #24 | 2016-05-20 | 75.277 mi |
| Registration #25 | 2016-05-20 | 75.277 mi |
| Registration #26 | 2016-05-20 | 75.277 mi |

| | | |
|------------------|------------|------------|
| Registration #27 | 2023-05-20 | 20,000,000 |
| Registration #28 | 2023-05-20 | 20,000,000 |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Number of seats4

Engine numberNOT KNOWN