



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-05-09
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	38
Total items failed	8

MOT #22 2023-05-10 15:52

MOT test number 321085329625

Result ✓ Passed

Next expiry date 2024-05-09

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 185/65x15 (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Clutch pedal rubber missing
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Power steering component has slight seepage from a component steering rack (2.1.5 (a))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #21 2022-04-19 15:46

MOT test number 603351519100

Result ✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened Sub frame/ axle assembly (5.3.3 (b) (i))

**MOT #20**

2022-04-19 11:44

**MOT test number**

842385168625

**Result****✗ Failed****Advice**

Rear Sub-frame corroded but not seriously weakened Sub frame/ axle assembly (5.3.3 (b) (i))

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail**

Power steering component leaking at rack (2.1.5 (a))

**Advice**

Heat shield loose

**Fail**

Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #19**

2021-03-16 09:42

**MOT test number**

779728948698

**Result****✓ Passed****Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #18**

2021-03-13 16:08

**MOT test number**

463006461886

**Result****✗ Failed****Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Fail**

Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

**MOT #17**

2020-03-24 10:47

**MOT test number**

465451065879

**Result****✓ Passed****Advice**

Crack in screen

**MOT #16** 2019-04-05 10:05**MOT test number** 731384449700**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2018-04-09 16:33**MOT test number** 236148307150**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #14** 2018-04-09 16:33**MOT test number** 262306795187**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Tyre has a tear, caused by separation or partial failure of its structure sidewall split (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #13** 2017-04-12 11:23**MOT test number** 716334375142**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust mounting poor

**MOT #12** 2017-04-12 11:23**MOT test number** 726995456054**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust mounting poor**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure out of shape (4.1.D.1b)**MOT #11** 2016-04-06 11:34**MOT test number** 726212494524**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2016-04-06 11:34**MOT test number** 519922810182**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2015-04-01 16:33**MOT test number** 375511795078**Result** ✓ Passed

**MOT #8** 2014-03-28 10:39**MOT test number** 487757784094**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear seats missing**MOT #7** 2014-03-28 10:39**MOT test number** 149587484042**Result** ✗ Failed**Notice** Rear seats missing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-03-28 15:50**MOT test number** 248757483026**Result** ✓ Passed**MOT #5** 2012-05-02 14:48**MOT test number** 469423822190**Result** ✓ Passed**Notice** Nearside front tyre wearing on outer edge**MOT #4** 2011-05-06 14:37**MOT test number** 859346021129**Result** ✓ Passed



<b>MOT #3</b>	2010-04-30 14:42
---------------	------------------

<b>MOT test number</b>	803340120160
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Notice</b>	Strap around exhaust back box corroded
---------------	--

<b>MOT #2</b>	2009-05-26 15:03
---------------	------------------

<b>MOT test number</b>	963966349155
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	O/s/f tyre scrubbing on inside
---------------	--------------------------------

<b>Notice</b>	N/s/f tyre scrubbing on inside
---------------	--------------------------------

<b>MOT #1</b>	2008-06-06 14:44
---------------	------------------

<b>MOT test number</b>	432878758187
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
9 May 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	9 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-06-10
Last registration	2023-05-10
Complete history	<a href="#">See info</a>



Registration #1	2005-06-10	26 mi
Registration #2	2008-06-06	20.333 mi
Registration #3	2009-05-26	24.894 mi
Registration #4	2010-04-30	30.371 mi
Registration #5	2011-05-06	36.739 mi
Registration #6	2012-05-02	42.146 mi
Registration #7	2013-03-28	47.016 mi
Registration #8	2014-03-28	66.589 mi
Registration #9	2015-04-01	81.761 mi
Registration #10	2016-04-06	87.386 mi
Registration #11	2016-04-06	87.386 mi
Registration #12	2017-04-12	95.980 mi
Registration #13	2018-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi
Registration #15	2020-05-20	101.277 mi
Registration #16	2021-05-20	101.277 mi
Registration #17	2022-05-20	101.277 mi
Registration #18	2023-05-10	101.277 mi
Registration #19	2023-05-10	101.277 mi
Registration #20	2023-05-10	101.277 mi
Registration #21	2023-05-10	101.277 mi
Registration #22	2023-05-10	101.277 mi
Registration #23	2023-05-10	101.277 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	DYUF4010622