



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT L1 H1 HDI SWB P/V
Colour	White
Year of manufacture	2010
Top speed	90 mph
0 - 60 mph	17.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-01
Pictures	29
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	9

MOT #16 2023-10-26 12:27

MOT test number 107500524558

Result ✓ Passed

Next expiry date 2024-10-25

- Advice** Power steering pipe/hose has slight seepage at steering rack (2.1.5 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15 2023-10-14 09:39

MOT test number 310695152161

Result ✗ Failed

- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Power steering pipe/hose has slight seepage at steering rack (2.1.5 (a))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2022-10-24 09:58

MOT test number

846406653882

Result

✓ Passed

Advice

Hydraulic leak, but not excessive at steering rack (8.4.1 (a) (i))

Advice

Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #13

2022-10-22 10:54

MOT test number

694951617697

Result

✗ Failed

Fail

Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Hydraulic leak, but not excessive at steering rack (8.4.1 (a) (i))

Advice

Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #12

2021-10-22 16:20

MOT test number

997667991915

Result

✓ Passed

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11

2020-11-27 14:47

MOT test number

395479012806

Result

✓ Passed

Advice

Nearside Front Lower Non obligatory mirror damaged glass cracked

Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #10**

2020-11-26 15:32

MOT test number

790050061347

Result**✗ Failed****Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Lower Non obligatory mirror damaged glass cracked**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9**

2019-11-27 12:33

MOT test number

663617826829

Result**✓ Passed****Minor** Front Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))**Advice** Nearside Front Lower Non obligatory mirror damaged**MOT #8**

2018-11-07 15:13

MOT test number

373232785028

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))**Advice** Nearside Front Lower Non obligatory mirror damaged**MOT #7**

2018-11-07 10:57

MOT test number

536665622452

Result**✗ Failed****Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))**Advice** Nearside Front Lower Non obligatory mirror damaged

**MOT #6** 2017-11-22 13:58**MOT test number** 171864120541**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened disc lipped (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened disc lipped (3.5.1i)**MOT #5** 2016-11-10 14:38**MOT test number** 343655150282**Result** ✓ Passed**MOT #4** 2015-11-10 11:08**MOT test number** 838938775057**Result** ✓ Passed**MOT #3** 2014-11-25 09:32**MOT test number** 118059424330**Result** ✓ Passed**MOT #2** 2013-11-22 09:50**MOT test number** 157206723379**Result** ✓ Passed



MOT #1	2013-11-12 10:24
MOT test number	117606013344
Result	✗ Failed
Fail	Offside Rear rear brake recording little or no effort (3.7.B.5a)
Fail	Offside Headlamp aim too low (1.8)
Fail	Parking brake lever has no reserve travel (3.1.6b)
Fail	Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 February
-------------------	------------------------

Days left	278
------------------	-----

MOT expiry date	25 October 2024
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-12-02
Last registration	2023-10-26
Complete history	See info



Registration #1	2010-12-02	9 mi
Registration #2	2013-11-12	30.979 mi
Registration #3	2013-11-22	31.228 mi
Registration #4	2014-11-25	38.268 mi
Registration #5	2015-11-10	44.275 mi
Registration #6	2016-11-10	51.539 mi
Registration #7	2017-11-22	58.363 mi
Registration #8	2018-11-07	63.927 mi
Registration #9	2018-11-07	63.927 mi
Registration #10	2019-11-07	63.927 mi
Registration #11	2019-11-07	63.927 mi
Registration #12	2019-11-07	63.927 mi
Registration #13	2019-11-07	63.927 mi
Registration #14	2019-11-07	63.927 mi
Registration #15	2019-11-07	63.927 mi
Registration #16	2019-11-07	63.927 mi
Registration #17	2019-11-07	63.927 mi
Registration #18	2019-11-07	63.927 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2194 mm
Height	1980 mm
Length	4805 mm
Kerb weight	1673 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JBBY0027041