





report date: 2024-03-29

General information

Make	BMW
Model	216 216D SPORT GRAN TOURER
Colour	White
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	116 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 сс
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-23

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #5	2024-04-20 09:56
MOT test number	467317753623
Result	✓ Passed
Next expiry date	2025-04-29

MOT #4		2024-04-19 13:52
MOT test	number	355387956755
Result		× Failed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2023-04-27 11:39
MOT test number	886219551706
Result	✓ Passed
Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	

CarCheck.co.uk page 3/11



MOT #2 2022-04-07 09:04

MOT test number 401133768861

Result ✓ Passed **Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i)) Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice **Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2021-04-30 14:42

MOT test number 481415954270

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners did check it in the premium report and see all owner registrations. Download the full report	

Diate changes	More info >
Plate changes Con in this phase if this PMW had different power has plates.	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-13
Last registration	2024-04-20
Complete history	See info



Registration #1	2018-03-13	16 mi
Registration #2	2021-04-30	33.448 mi
Registration #3		11.777 es
Registration #4	2022-04-07	35.441 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
S0569	

Dimensions & weight

Width	2038 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1470 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	51
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	39895276

CarCheck.co.uk page 11/11