



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-08-10
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	19
Total items failed	8

MOT #17 2023-08-03 12:18

MOT test number 154589692096

Result ✓ Passed

Next expiry date 2024-08-23

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2022-08-24 14:46

MOT test number 584840778320

Result ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-08-16 08:32

MOT test number 215981649858

Result ✗ Failed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Anti-roll bar pin or bush likely to become detached bolt or pin missing/snapped (5.3.4 (a) (ii))



MOT #14	2021-08-18 12:34
MOT test number	419568660814
Result	✓ Passed

MOT #13	2020-07-30 11:51
MOT test number	681556271760
Result	✓ Passed

MOT #12	2020-07-29 08:26
MOT test number	690903856938
Result	✗ Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #11	2019-03-29 11:54
MOT test number	556100831003
Result	✓ Passed

MOT #10	2019-03-26 11:54
MOT test number	282716342450
Result	✗ Failed
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #9	2018-04-11 08:25
MOT test number	367439454647
Result	✓ Passed
Advice Front registration plate delaminated but not likely to be misread (6.3.1d)	
Advice Rear Direction indicators slightly discoloured (1.4.A.2f)	

**MOT #8** 2018-04-11 08:25**MOT test number** 896235548983**Result** ✗ Failed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2017-04-03 13:54**MOT test number** 620252699742**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake fluctuating, but not excessively both (3.7.B.3)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2017-04-03 13:54**MOT test number** 495029028375**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake fluctuating, but not excessively both (3.7.B.3)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2016-04-06 14:13**MOT test number** 136627701700**Result** ✓ Passed



MOT #4	2016-04-06 09:03
---------------	------------------

MOT test number	243531088084
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Headlamp aim too low (1.8)
-------------	------------------------------------

Fail	Nearside Headlamp aim too low (1.8)
-------------	-------------------------------------

MOT #3	2015-04-23 16:54
---------------	------------------

MOT test number	107043915152
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-05-02 15:00
---------------	------------------

MOT test number	439402724128
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-05-07 12:09
---------------	------------------

MOT test number	219487023156
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Emissions too clean to register on smoke meter
---------------	------------------------------------------------

Notice	Bad cut in nearside front tyre sidewall
---------------	-----------------------------------------



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
23 August 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-05-31
Last registration	2023-08-03
Complete history	See info



Registration #1	2010-05-31	9 mi
Registration #2	2013-05-07	22.127 mi
Registration #3	2014-05-02	28.417 mi
Registration #4	2015-04-23	33.404 mi
Registration #5	2016-04-06	38.496 mi
Registration #6	2016-04-06	38.496 mi
Registration #7	2017-04-03	45.017 mi
Registration #8	2017-04-03	45.017 mi
Registration #9	2018-04-11	52.185 mi
Registration #10	2018-04-11	52.185 mi
Registration #11	2019-05-29	59.377 mi
Registration #12	2019-05-29	59.377 mi
Registration #13	2020-05-29	66.569 mi
Registration #14	2020-05-29	66.569 mi
Registration #15	2021-05-29	73.761 mi
Registration #16	2021-05-29	73.761 mi
Registration #17	2022-05-29	80.953 mi
Registration #18	2022-05-29	80.953 mi
Registration #19	2023-08-03	88.145 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602