



**K44GPB**


report date: 2024-03-29

General information

Make	BENTLEY
Model	CONTINENTAL GT
Colour	Silver
Year of manufacture	2005
Top speed	198 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	550 BHP
Max. torque	650 Nm at 1.600 rpm
Engine capacity	5.998 cc
Cylinders	12
Fuel type	Petrol
Consumption city	10.8 mpg
Consumption extra urban	23.7 mpg
Consumption combined	16.5 mpg
CO2 emission	410 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-13
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-05-07
MOT pass rate	100 %
MOT passed	17
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #17	2024-04-24 13:46
MOT test number	692317129354
Result	✓ Passed
Next expiry date	2025-05-07
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #16	2023-05-08 13:41
MOT test number	172523157337
Result	✓ Passed

MOT #15	2022-04-14 10:00
MOT test number	247437290620
Result	✓ Passed

MOT #14	2021-09-07 06:52
MOT test number	369402039288
Result	✓ Passed

MOT #13	2020-01-13 14:54
MOT test number	171816709129
Result	✓ Passed

**MOT #12** 2019-01-03 11:31**MOT test number** 863602862564**Result** ✓ Passed**MOT #11** 2018-01-09 11:17**MOT test number** 712817189318**Result** ✓ Passed**MOT #10** 2017-01-12 16:03**MOT test number** 384857258325**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-01-19 16:42**MOT test number** 179854332231**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-12-17 11:25**MOT test number** 318541454308**Result** ✓ Passed**MOT #7** 2014-01-08 11:59**MOT test number** 979948504018**Result** ✓ Passed**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



<b>MOT #6</b>	2012-12-13 15:04
---------------	------------------

<b>MOT test number</b>	366118442319
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-01-05 15:16
---------------	------------------

<b>MOT test number</b>	399145002090
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Both rear tyres wearing towards limit
---------------	---------------------------------------

<b>MOT #4</b>	2011-01-12 09:38
---------------	------------------

<b>MOT test number</b>	445892311063
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-01-28 13:19
---------------	------------------

<b>MOT test number</b>	701748920095
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2009-02-23 16:29
---------------	------------------

<b>MOT test number</b>	451274359053
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2008-04-29 13:49
---------------	------------------

<b>MOT test number</b>	333820928125
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
7 May 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	7 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this BENTLEY. See if, where and when this BENTLEY had damage and the car repair costs. We also check if this BENTLEY was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BENTLEY salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BENTLEY in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this BENTLEY? How many owners did this BENTLEY have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this BENTLEY had different number plates.

Number of plates	1
Current registration	<b>K44GPB</b>
Plate since	2019-03-29
Current registration	<b>K44GPB</b>
Plate since	2019-03-29

More info >



Finance check

Check if this BENTLEY is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BENTLEY has been settled.

If not, and you buy this BENTLEY then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BENTLEY is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-04-15
Last registration	2024-04-24
Complete history	<a href="#">See info</a>



Registration #1	2005-04-15	23 mi
Registration #2	2008-04-29	3.645 mi
Registration #3	2009-02-23	4.407 mi
Registration #4	2010-01-28	11.419 mi
Registration #5	2011-01-12	16.827 mi
Registration #6	2012-01-05	23.154 mi
Registration #7	2012-12-13	27.967 mi
Registration #8	2014-01-08	34.169 mi
Registration #9	2014-12-17	39.705 mi
Registration #10	2016-01-19	44.830 mi
Registration #11	2016-01-19	48.300 mi
Registration #12	2016-01-19	48.300 mi
Registration #13	2016-01-19	48.300 mi
Registration #14	2016-01-19	48.300 mi
Registration #15	2016-01-19	48.300 mi
Registration #16	2016-01-19	48.300 mi
Registration #17	2016-01-19	48.300 mi
Registration #18	2016-01-19	48.300 mi
Registration #19	2016-01-19	48.300 mi

More info >



Dimensions & weight

Width	1965 mm
Height	1390 mm
Length	4807 mm
Wheel base	2745 mm
Kerb weight	2410 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	008795