



P537HAU

report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 14 CHAS SWB TD
Colour	White
Year of manufacture	1997
Gearbox	-Manual

Engine & fuel consumption

Engine capacity	2.500 cc
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-10-07
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	85
Total items failed	22

MOT #24	2023-09-15 11:08
MOT test number	315730208003
Result	✓ Passed
Next expiry date	2024-10-07
Advice	Vehicle covered in underseal throughout the underside

MOT #23	2022-09-27 12:32
MOT test number	174238062133
Result	✓ Passed
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #22	2022-09-27 12:32
MOT test number	481816753724
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #21	2021-10-08 10:31
MOT test number	803218276931
Result	✓ Passed

**MOT #20**

2020-11-17 17:44

MOT test number

738675115346

Result**✗ Failed**

Fail Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength crossmember mounting point (5.3.6 (a) (i))

Advice Both hand brake cable mounting points badly deteriorating keep under observation

Minor Offside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Underside badly deteriorating keep under observation

Fail Rear Brake load sensing valve inoperative and ABS not fitted or inoperative (1.1.17 (c) (ii))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail Offside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength crossmember mount (5.3.6 (a) (i))

Fail Brake hose ferrule excessively corroded all front [4] (1.1.12 (f) (i))

Advice Reversing light inoperative

Minor Nearside Front Brake pipe inadequately clipped or supported both flexi mounting point corroded (1.1.11 (d) (i))

Advice Brake pipe corroded, covered in grease or other material all pipes across rear beam axle and front to rear coated in grease (1.1.11 (c))

Fail Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced step area inner (7.1.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))



MOT #192019-10-15 15:38

MOT test number948952394999

Result		✓ Passed
Advice	Brake hose has slight corrosion to ferrule All front keep under observation (1.1.12 (f) (i))	
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Reverse light inoperative	
Advice	Offside Front Crossmember mounting point deteriorating	
Advice	Brake pipe corroded, covered in grease or other material All front and rear (1.1.11 (c))	
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Vehicle underside badly deteriorating keep under observation	

**MOT #18**

2019-10-14 11:09

MOT test number

276241258928

Result**✗ Failed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Vehicle underside badly deteriorating keep under observation

Advice

Brake pipe corroded, covered in grease or other material All front and rear (1.1.11 (c))

Advice

Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Minor

Offside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice

Reverse light inoperative

Fail

Nearside Front Headlamp aim too high (4.1.2 (a))

Advice

Offside Front Crossmember mounting point deteriorating

Advice

Brake hose has slight corrosion to ferrule All front keep under observation (1.1.12 (f) (i))

Advice

Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #17

2018-08-10 08:12

MOT test number

439205308095

Result**✓ Passed****Advice**

Vehicle underside deteriorating keep under observation

Advice

Brake pipe corroded, covered in grease or other material front and rear (1.1.11 (c))

Advice

Nearside Rear Reversing light inoperative

Advice

Offside Front Brake pipe mounting points inner wheel arch deteriorating

Advice

Offside Front Upper Marker light inoperative

Advice

All front flexi hoses ferrules badly deteriorated

**MOT #16**

2018-08-06 11:14

MOT test number

500958507104

Result**✗ Failed**

- Advice** All front flexi hoses ferrules badly deteriorated
- Fail** Horn not working (7.7 (a) (ii))
- Advice** Vehicle underside deteriorating keep under observation
- Advice** Nearside Rear Reversing light inoperative
- Fail** Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))
- Advice** Offside Front Brake pipe mounting points inner wheel arch deteriorating
- Advice** Brake pipe corroded, covered in grease or other material front and rear (1.1.11 (c))
- Advice** Offside Front Upper Marker light inoperative

MOT #15

2017-07-25 15:00

MOT test number

612370500202

Result**✓ Passed**

- Advice** Power steering pipes are corroded
- Advice** O/s & n/s front flexible brake pipe ferrules are corroded
- Advice** There is quite a bit of rust under this vehicle it should all be kept under observation
- Advice** Front high level side lamps inoperative
- Advice** Some front metal brake pipes are corroded
- Advice** Front flexible brake pipe brackets are corroded



MOT #14

2016-07-12 15:04

MOT test number

310612373233

Result

✓ Passed

- Advice** Rear suspension hanger brackets corroded
- Advice** O/s & n/s front metal brake pipes are corroded
- Advice** Some exhaust rubbers are missing
- Advice** Sill and chassis leg corrosion advancing requiring strict monitoring
- Advice** Some power steering pipes are quite badly corroded
- Advice** Wiring close to rear suspension requires tidying up
- Advice** General structural corrosion present requires strict monitoring

MOT #13

2015-07-31 17:48

MOT test number

398012515266

Result

✓ Passed

- Notice** Drivers step and sill corroded and holed
- Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)
- Notice** Both front top marker lamps not working
- Advice** Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #12**

2015-07-29 09:48

MOT test number

509080115281

Result

✗ Failed

- Fail** Rear Brake hose ferrule excessively corroded (3.6.B.4e)
- Notice** Drivers step and sill corroded and holed
- Fail** Rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Both front top marker lamps not working
- Fail** Offside Brake cable insecure (3.5.1d)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #11

2014-06-13 11:07

MOT test number

259624864118

Result

✓ Passed

- Advice** Nearside Front Vehicle structure has slight corrosion (6.1.A.1)
- Notice** Brake pipes coated in grease,unable to do full check
- Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Vehicle structure has slight corrosion (6.1.A.1)
- Notice** Nearside front top marker lamp inoperative
- Notice** Exhaust rubber mount missing
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

**MOT #10**

2014-06-11 12:20

MOT test number

916592864143

Result**✗ Failed****Advice** Nearside Front Vehicle structure has slight corrosion (6.1.A.1)**Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Nearside front top marker lamp inoperative**Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)**Notice** Exhaust rubber mount missing**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Vehicle structure has slight corrosion (6.1.A.1)**Fail** Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear position lamp(s) insecure (1.1.A.3a)**Notice** Brake pipes coated in grease,unable to do full check**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #9**

2013-06-11 09:30

MOT test number

608792763147

Result**✓ Passed****Notice** O/s/f step corroded not in prescribed area**Notice** Brake pipes coated in grease**MOT #8**

2012-06-12 11:18

MOT test number

259314062433

Result**✓ Passed****Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #7** 2011-06-08 15:31**MOT test number** 786639451171**Result** ✓ Passed**MOT #6** 2010-06-09 13:32**MOT test number** 300980060187**Result** ✓ Passed**MOT #5** 2010-06-04 11:20**MOT test number** 780205150130**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #4** 2009-03-04 09:51**MOT test number** 194393669477**Result** ✓ Passed**MOT #3** 2008-03-18 12:32**MOT test number** 504578878095**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Under side of vehicle very rusty and dry**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**MOT #2** 2007-03-15 10:03**MOT test number** 890244277092**Result** ✓ Passed



MOT #1	2006-03-22 10:56
MOT test number	210951886044
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 October 2024

Tax status	Valid until 1 August
-------------------	----------------------

Days left	94
------------------	----

MOT expiry date	7 October 2024
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1997-04-25
Last registration	2023-09-15
Complete history	See info



Registration #1	1997-04-25	22 mi
Registration #2	2006-03-22	24.474 mi
Registration #3	2007-03-15	26.379 mi
Registration #4	2008-03-18	28.024 mi
Registration #5	2009-03-04	29.268 mi
Registration #6	2010-06-04	31.935 mi
Registration #7	2010-06-09	31.940 mi
Registration #8	2011-06-08	35.590 mi
Registration #9	2012-06-12	40.431 mi
Registration #10	2013-06-11	43.184 mi
Registration #11	2014-06-11	44.111 mi
Registration #12	2014-06-13	44.112 mi
Registration #13	2015-07-29	44.428 mi
Registration #14	2016-06-20	45.377 mi
Registration #15	2017-06-20	46.327 mi
Registration #16	2018-06-20	47.277 mi
Registration #17	2019-06-20	48.227 mi
Registration #18	2020-06-20	49.177 mi
Registration #19	2021-06-20	50.127 mi
Registration #20	2022-06-20	51.077 mi
Registration #21	2023-06-20	52.027 mi
Registration #22	2024-06-20	52.977 mi
Registration #23	2025-06-20	53.927 mi
Registration #24	2026-06-20	54.877 mi
Registration #25	2027-06-20	55.827 mi



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1998 mm
Max. allowed weight	3200 kg

Additional information

Number of axles	2
Engine number	2313667