



UK

PEI0KZV

report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT #13

2023-12-06 12:14

MOT test number

593124459493

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 175/65R14 (5.2.3 (e))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 175/65R14 (5.2.3 (d) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear axle corroded but not seriously weakened
- MAJOR** Nearside Front Headlamp insecure (4.1.1 (c))
- Advice** Front Shock absorbers has light misting of oil both (5.3.2 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing 175/65R14 (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- MAJOR** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Front Windscreen washer provides insufficient washer liquid both (3.5 (a))
- Advice** Rear exhaust back box corroded
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))



MOT #12

2022-10-13 15:57

MOT test number

580824450329

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear axle corroded
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge smooth (5.2.3 (e))
- Advice** Rear Exhaust noisy corroded (8.1.1 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Items removed from driver's view prior to test
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge smooth (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #11**

2022-10-13 15:57

MOT test number

604907167015

Result**✗ Failed**

- Advice** Front Items removed from driver's view prior to test
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Exhaust noisy corroded (8.1.1 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge smooth (5.2.3 (e))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear axle corroded
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge smooth (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10

2021-02-25 11:19

MOT test number

315500658278

Result**✓ Passed**

- Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9** 2020-03-17 10:21**MOT test number** 340239176731**Result** ✓ Passed**Advice** Exhaust deteriorated**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**Advice** Front Lower Suspension arm ball joint has slight play both sides (5.3.4 (a) (i))**Advice** Rear Shock absorbers has a slightly worn bush both sides (5.3.2 (c))**MOT #8** 2019-03-19 09:53**MOT test number** 301113107171**Result** ✓ Passed**Advice** Exhaust deteriorated**MOT #7** 2018-03-20 13:42**MOT test number** 308435864553**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** EXHAUST CORRODED**MOT #6** 2017-03-20 13:05**MOT test number** 769692286377**Result** ✓ Passed**MOT #5** 2017-03-20 10:58**MOT test number** 446552546652**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit change as soon as possible (4.1.E.1)



MOT #4	2016-03-21 10:19
---------------	------------------

MOT test number	350282685409
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit sidewalls cracking (4.1.E.1)
---------------	-------------------------------------------------------------------------------

Advice	Nearside Rear tyre sidewalls cracking
---------------	---------------------------------------

MOT #3	2015-03-24 15:58
---------------	------------------

MOT test number	628083985092
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Offside front and nearside rear tyres deteriorated starting to crack
---------------	----------------------------------------------------------------------

MOT #2	2014-01-28 09:28
---------------	------------------

MOT test number	619018524039
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-04-25 13:08
---------------	------------------

MOT test number	847265213170
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	PE10KZV
Plate since	2019-03-29
Current registration	PE10KZV
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-24
Last registration	2023-12-06
Complete history	See info



Registration #1	2010-03-24	17 mi
Registration #2	2013-04-25	10.372 mi
Registration #3	2014-01-28	16.133 mi
Registration #4	2015-03-24	17.536 mi
Registration #5	2016-03-21	19.943 mi
Registration #6	2017-03-20	22.290 mi
Registration #7	2017-03-20	22.290 mi
Registration #8	2018-03-20	24.595 mi
Registration #9	2019-03-20	26.899 mi
Registration #10	2020-03-20	29.203 mi
Registration #11	2021-03-20	31.507 mi
Registration #12	2022-03-20	33.811 mi
Registration #13	2023-03-20	36.115 mi
Registration #14	2024-03-20	38.419 mi
Registration #15	2025-03-20	40.723 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203