



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-02
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-01
Pictures	31
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	35
Total items failed	4

MOT #19	2023-10-10 13:01
MOT test number	992324628281
Result	✓ Passed
Next expiry date	2024-10-19
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-10-10 10:42
MOT test number	334677475507
Result	✗ Failed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
MAJOR	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

MOT #17	2022-10-12 15:47
MOT test number	854797746708
Result	✓ Passed

**MOT #16** 2022-10-12 13:05**MOT test number** 866230523276**Result** ✗ Failed**MAJOR** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #15** 2021-10-20 13:14**MOT test number** 278916518063**Result** ✓ Passed**MOT #14** 2020-12-10 11:13**MOT test number** 906743538287**Result** ✓ Passed**Advice** Front Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13**

2020-12-09 12:35

MOT test number

280939150694

Result**✗ Failed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- Advice** Front Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12

2019-12-09 08:36

MOT test number

758035840312

Result**✓ Passed**

- Advice** Child Seat fitted not allowing full inspection of adult belt

MOT #11

2019-12-06 15:16

MOT test number

462575179217

Result**✗ Failed**

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2018-12-11 11:06**MOT test number** 857076977851**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2017-12-06 16:05**MOT test number** 117994353237**Result** ✓ Passed**MOT #8** 2017-12-06 16:05**MOT test number** 181906435780**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #7** 2017-04-13 08:28**MOT test number** 944279785490**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner faces (3.5.1i)**MOT #6** 2016-01-07 12:47**MOT test number** 831073142047**Result** ✓ Passed**MOT #5** 2015-01-06 15:57**MOT test number** 995616305060**Result** ✓ Passed

**MOT #4** 2014-01-16 14:54**MOT test number** 555966014038**Result** ✓ Passed**MOT #3** 2013-06-22 11:55**MOT test number** 429453573163**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-06-22 09:48**MOT test number** 857583773139**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Inner Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-06-22 11:56**MOT test number** 139684472174**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-07-03
Last registration	2023-10-10
Complete history	See info



Registration #1	2009-07-03	11 mi
Registration #2	2012-06-22	37.681 mi
Registration #3	2013-06-22	64.507 mi
Registration #4	2013-06-22	64.507 mi
Registration #5	2014-01-16	75.986 mi
Registration #6	2015-01-06	80.758 mi
Registration #7	2016-01-07	84.250 mi
Registration #8	2017-04-13	89.424 mi
Registration #9	2017-12-06	90.530 mi
Registration #10	2017-12-06	90.530 mi
Registration #11	2018-12-11	103.030 mi
Registration #12	2019-01-01	103.030 mi
Registration #13	2019-01-01	103.030 mi
Registration #14	2019-01-01	103.030 mi
Registration #15	2019-01-01	103.030 mi
Registration #16	2019-01-01	103.030 mi
Registration #17	2019-01-01	103.030 mi
Registration #18	2019-01-01	103.030 mi
Registration #19	2019-01-01	103.030 mi
Registration #20	2019-01-01	103.030 mi
Registration #21	2019-01-01	103.030 mi
Registration #22	2019-01-01	103.030 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	613349
---------------	--------