




report date: 2024-03-28

## General information

Make	VOLVO
Model	C30 D R-DESIGN SE
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-28
Pictures	0
Listing price	<a href="#">View report</a>

source: theaa.com



## MOT history

MOT expiry date	2024-08-11
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	20
Total items failed	9

MOT #19	2023-08-12 12:50
MOT test number	745350018133
Result	✓ Passed
Next expiry date	2024-08-11

MOT #18	2022-11-19 12:58
MOT test number	448239852272
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Service brake fluctuating, but not excessively both sides (1.2.1 (e))

MOT #17	2021-11-10 15:26
MOT test number	799812565338
Result	✓ Passed

MOT #16	2021-05-24 08:03
MOT test number	212281218120
Result	✓ Passed

**MOT #15** 2021-05-20 15:43**MOT test number** 111083792518**Result** ✓ Passed**Advice** Nearside fuse box under dash hung down**MOT #14** 2021-05-10 14:49**MOT test number** 145572997977**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside fuse box under dash hung down**Fail** Offside Front Wheel bearing rough when rotated very noisy (5.1.3 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13** 2021-01-13 17:36**MOT test number** 348068010334**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #12** 2019-07-16 14:45**MOT test number** 356868178651**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2019-07-15 14:51**MOT test number** 803452259705**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2018-07-18 15:00**MOT test number** 356918468321**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-09-25 14:49**MOT test number** 192304869558**Result** ✓ Passed**MOT #8** 2017-09-25 14:04**MOT test number** 837805352801**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #7** 2016-09-05 09:28**MOT test number** 650614700960**Result** ✓ Passed**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)

**MOT #6** 2015-09-23 10:32**MOT test number** 681133435921**Result** ✓ Passed**Advice** Back box double skin corroded**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Lower rear (2.4.G.2)**Advice** Front Tyre worn close to the legal limit Both sides inner edge walls (4.1.E.1)**MOT #5** 2015-09-04 16:58**MOT test number** 275201226953**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit Both inner side wall (4.1.E.1)**Fail** Windscreen wiper not operating automatically when switched on (8.2.1b)**MOT #4** 2014-09-10 11:25**MOT test number** 929033554240**Result** ✓ Passed**MOT #3** 2014-09-10 11:25**MOT test number** 145173054237**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #2** 2012-12-04 14:23**MOT test number** 155949132313**Result** ✓ Passed



MOT #1	2012-12-03 11:39
MOT test number	346588232357
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Rear Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
11 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	11 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-28
Last registration	2023-08-12
Complete history	<a href="#">See info</a>



Registration #1	2009-11-28	6 mi
Registration #2	2012-12-03	30.668 mi
Registration #3	2012-12-04	30.673 mi
Registration #4	2014-09-10	44.270 mi
Registration #5	2015-09-04	52.718 mi
Registration #6	2015-09-23	52.823 mi
Registration #7	2016-09-05	63.380 mi
Registration #8	2017-09-25	73.306 mi
Registration #9	2017-09-25	73.310 mi
Registration #10	2018-07-18	79.357 mi
Registration #11	2019-05-20	85.397 mi
Registration #12	2019-05-20	85.397 mi
Registration #13	2019-05-20	85.397 mi
Registration #14	2019-05-20	85.397 mi
Registration #15	2019-05-20	85.397 mi
Registration #16	2019-05-20	85.397 mi
Registration #17	2019-05-20	85.397 mi
Registration #18	2019-05-20	85.397 mi
Registration #19	2019-05-20	85.397 mi
Registration #20	2019-05-20	85.397 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1430 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	639928