



HJ60YDE

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 280 MWB LR P/V 85
Colour	Silver
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT #12 2019-11-11 17:31

MOT test number 988001643900

Result ✓ Passed

Next expiry date 2020-11-10

- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2019-11-11 13:57

MOT test number

438560705158

Result**✗ Failed**

- Advice** Offside Front Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
- Fail** Fuel hose damaged by tank (6.1.3 (c) (ii))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Stop lamp(s) adversely affected by the operation of another lamp side light brighter than brake light (4.3.3 (b))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

**MOT #10**

2018-10-23 11:17

MOT test number

206425832149

Result

✓ Passed

- Advice** Offside Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2018-10-22 10:08

MOT test number

804007405415

Result

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Brake lining(s) wear indicator illuminated (1.1.13 (a) (i))
- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Fuel hose damaged by tank (6.1.3 (c) (ii))
- Advice** Offside Seat belt buckle slightly damaged (7.1.2 (d))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2017-10-30 16:19**MOT test number** 438881072977**Result** Passed**MOT #7** 2017-10-30 13:38**MOT test number** 444466840451**Result** Failed

- Fail** Front Windscreen washer provides insufficient washer liquid fluid (8.2.3)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Registration plate lamp not illuminating the registration plate (1.1.C.1e)

MOT #6 2016-11-10 17:53**MOT test number** 437979210778**Result** Passed**MOT #5** 2016-11-10 17:10**MOT test number** 155882259072**Result** Failed

- Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)
- Fail** Offside Rear fog lamp adversely affected by the operation of another lamp (1.3.2f)

MOT #4 2015-11-05 15:23**MOT test number** 282875985493**Result** Passed

**MOT #3** 2015-11-05 10:22**MOT test number** 886024115238**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #2** 2014-11-07 16:20**MOT test number** 139271714311**Result** ✓ Passed**MOT #1** 2013-10-15 12:02**MOT test number** 526938283244**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-10-28
Last registration	2019-11-11
Complete history	See info



Registration #1	2010-10-28	28 mi
Registration #2	2013-10-15	6.993 mi
Registration #3	2014-11-07	9.940 mi
Registration #4	2015-11-05	12.951 mi
Registration #5	2015-11-05	12.951 mi
Registration #6	2016-11-10	31.437 mi
Registration #7	2016-11-10	31.437 mi
Registration #8	2019-11-11	31.437 mi
Registration #9	2019-11-11	31.437 mi
Registration #10	2019-11-11	31.437 mi
Registration #11	2019-11-11	31.437 mi
Registration #12	2019-11-11	31.437 mi
Registration #13	2019-11-11	31.437 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	1985 mm
Length	5230 mm
Kerb weight	1669 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	AG08523