





report date: 2024-03-28

General information

Make	FORD	
Model	MONDEO EDGE TDCI 125	
Colour	Grey	
Year of manufacture	2007	
Top speed	124 mph	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2020-09-20
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #11	2019-09-20 15:42
MOT test number	839827278903
Result	✓ Passed
Next expiry date	2020-09-20

MOT #10	2018-09-21 14:29
MOT test number	810081922371
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #9		2017-07-19 13:57
MOT test	number	773710596421
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Body has slight corrosion (6.1.B.2)	
Advice	Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Body has slight corrosion (6.1.B.2)	
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	

CarCheck.co.uk page 2/11



MOT #8 2017-07-14 13:14

MOT test number 576498412581

Result X Failed

Advice Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Body has slight corrosion (6.1.B.2)

Advice Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

Fail Nearside Rear Wheel stud(s) missing (4.2.A.1e)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Horn not working (1.6.2a)

Advice Rear Body has slight corrosion (6.1.B.2)

MOT #7 2014-09-11 13:49

MOT test number 398034054464

MOT #6 2013-08-06 16:09

MOT test number 199458213253

Result
✓ Passed

MOT #5 2012-08-14 09:49

MOT test number 628327222251

Result ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Nearside Front Trailing arm rubber bush deteriorated but not resulting in excessive movement

Advice (2.4.G.2)

CarCheck.co.uk page 3/11



Fail

NU57EHL

report date: 2024-03-28

MOT #4 2011-09-02 12:04 **MOT test number** 739435741221 Result ✓ Passed **MOT** #3 2011-09-02 09:15 **MOT** test number 319765141416 Result × Failed Pass with rectification Offside Windscreen washer provides insufficient washer liquid (8.2.3) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2 2010-08-31 09:59 **MOT** test number 891733940288 Result ✓ Passed **MOT #1** 2010-08-31 09:59 **MOT test number** 351953640468 Result × Failed **Pass with rectification** Offside Headlamp aim too high (1.8) Pass with rectification Nearside Headlamp aim too high (1.8)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax expired: 31 October 2020

X MOT

Expired: 20 September 2020

Tax status	Expired at 31 October 2020
Days left	1276 days too late
MOT expiry date	20 September 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
HARMAN CONTRACTOR CONT	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NE AND
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2007-09-05
Last registration	2019-09-20
Complete history	See info



Registration #1	2007-09-05	27 mi
Registration #2	2010-08-31	56.721 mi
Registration #3	2011-09-02	75.298 mi
Registration #4	2011-09-02	75.298 mi
Registration #5	2012-08-14	89.052 mi
Registration #6	2013-08-06	95.180 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11



NU57EHL

report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4844 mm
Wheel base	2754 mm
Max. allowed weight	2150 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number Carcheck.co.uk	7U27890 page 11/11