



General information

Make	MAZDA
Model	2 SPORT
Colour	Silver
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	137 Nm at 4.000 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-08
Pictures	36
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-28
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	22
Total items failed	5

MOT #15	2023-05-18 15:09
MOT test number	942980027250
Result	✓ Passed
Next expiry date	2024-05-28
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14	2023-05-10 09:47
MOT test number	158099737908
Result	✗ Failed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #13	2022-05-12 14:06
MOT test number	619644627247
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2022-05-11 10:41**MOT test number** 372347206273**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2021-05-29 13:34**MOT test number** 696257987096**Result** ✓ Passed**MOT #10** 2020-09-14 11:39**MOT test number** 262830665710**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear axle corroded**MOT #9** 2019-05-28 15:04**MOT test number** 749285273377**Result** ✓ Passed**MOT #8** 2019-05-28 13:01**MOT test number** 926786533490**Result** ✗ Failed**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #7** 2018-05-26 11:10**MOT test number** 498363876099**Result** ✓ Passed

- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #6 2017-06-24 11:29**MOT test number** 213106237052**Result** ✓ Passed

- Advice** Wear in n/s/f lower ball joint(borderline pass)

MOT #5 2016-06-20 15:00**MOT test number** 197212232627**Result** ✓ Passed

- Advice** Drivers door check strap broken

MOT #4 2015-06-26 15:19**MOT test number** 676157675190**Result** ✓ Passed

**MOT #3** 2015-06-26 10:36**MOT test number** 576157975181**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2014-07-05 15:52**MOT test number** 839286284123**Result** ✓ Passed**MOT #1** 2013-06-22 10:18**MOT test number** 226403573161**Result** ✓ Passed**Notice** Tyre pressures were incorrect - set prior to test**Notice** O/s/r tyre is punctured close to inner sidewall



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
28 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	28 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-01
Last registration	2023-05-18
Complete history	See info



Registration #1	2010-07-01	26 mi
Registration #2	2013-06-22	19.716 mi
Registration #3	2014-07-05	26.821 mi
Registration #4	2015-06-26	33.952 mi
Registration #5	2015-06-26	33.952 mi
Registration #6	2016-06-20	41.027 mi
Registration #7	2017-06-24	49.256 mi
Registration #8	2018-05-26	55.852 mi
Registration #9	2019-05-28	63.813 mi
Registration #10	2020-05-28	71.774 mi
Registration #11	2021-05-28	79.735 mi
Registration #12	2022-05-28	87.696 mi
Registration #13	2023-05-18	95.657 mi
Registration #14	2024-03-29	103.618 mi
Registration #15	2024-03-29	111.579 mi
Registration #16	2024-03-29	119.540 mi
Registration #17	2024-03-29	127.501 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3895 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1460 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	ZY 605065