




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Grey
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E







Internet history

Entry 2

Date	2021-10-26
Pictures	45
Listing price	<a href="#">View report</a>





**Video viewing**



Book a video viewing with one of our team.  
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)

source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-10-25
Pictures	45
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	3
Total items failed	6

MOT #14	2023-10-25 12:48
MOT test number	149277573362
Result	✓ Passed
Next expiry date	2024-10-24

MOT #13	2023-07-05 10:05
MOT test number	257365748252
Result	✓ Passed

MOT #12	2023-07-05 10:05
MOT test number	110632216990
Result	✗ Failed
<b>Pass with rectification</b> Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #11	2023-01-27 13:43
MOT test number	387721024248
Result	✓ Passed

**MOT #10** 2023-01-27 12:22**MOT test number** 124088812004**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2021-12-20 16:49**MOT test number** 705815528030**Result** ✓ Passed**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2021-01-12 16:17**MOT test number** 736447380699**Result** ✓ Passed**MOT #7** 2021-01-12 13:34**MOT test number** 624558551490**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Rear Tyre has ply or cords damaged both (5.2.3 (d) (ii))**Fail** Anti-lock braking system warning lamp does not illuminate (1.6 (a))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #6** 2019-06-20 10:21**MOT test number** 399507919396**Result** ✓ Passed



<b>MOT #5</b>	2018-04-12 08:49
<b>MOT test number</b>	488599842102
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2017-04-13 09:45
<b>MOT test number</b>	172248864336
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2016-10-18 10:06
<b>MOT test number</b>	604575001455
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2016-04-21 09:42
<b>MOT test number</b>	390736273648
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2015-09-17 14:35
<b>MOT test number</b>	188975965040
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>CK62LUF</b>
Plate since	2019-06-29
Current registration	 <b>CK62LUF</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-10-16
Last registration	2023-10-25
Complete history	<a href="#">See info</a>



Registration #1	2012-10-16	24 mi
Registration #2	2015-09-17	20.938 mi
Registration #3	2016-04-21	23.258 mi
Registration #4	2016-10-18	25.325 mi
Registration #5	2017-04-13	27.391 mi
Registration #6	2018-04-12	31.455 mi
Registration #7	2019-06-20	34.935 mi
Registration #8	2021-01-12	38.765 mi
Registration #9	2021-01-12	38.765 mi
Registration #10	2022-01-20	39.377 mi
Registration #11	2022-01-20	39.377 mi
Registration #12	2022-01-20	39.377 mi
Registration #13	2022-01-20	39.377 mi
Registration #14	2022-01-20	39.377 mi
Registration #15	2022-01-20	39.377 mi
Registration #16	2022-01-20	39.377 mi
Registration #17	2022-01-20	39.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAYCK90899