





report date: 2024-03-28

# General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	White
Year of manufacture	2013
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Semi Auto

# Engine & fuel consumption

Power	130 kW / 177 HP / 175 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/12




Internet history

# Entry 3

Date 2023-01-06

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

## Entry 2

Date	2021-07-22
Pictures	2
Listing price	View report





source: cargurus.co.uk

#### Entry 1

Date	2021-07-21
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

Fail

MOT expiry date	2024-07-19
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	16
Total items failed	2

MOT #10		2023-07-20 15:21
MOT test	number	457789777139
Result		✓ Passed
Next expi	ry date	2024-07-19
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2022-07-16 09:18
MOT test number	906632976420
Result	✓ Passed
MOT #8	2022-07-15 10:40
MOT test number	676570146978
Result	<b>X</b> Failed
Fail Offside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-08-17 15:28
MOT test number	620862465915
Result	<b>✓</b> Passed

Nearside Front Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2020-12-15 17:52

**MOT test number** 186208498022

**Result** ✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

MOT #5 2019-06-22 15:34

**MOT test number** 250285554314

**Result** ✓ Passed

MOT #4 2018-06-27 14:46

**MOT test number** 353891542271

MOT #3 2018-04-25 10:43

MOT test number 406316392406

Result 

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Offside Rear Tyre wearing unevenly on inner shoulder

**Advice** Towball/hitch not fitted at time of test

**MOT #2** 2017-04-27 10:29

MOT test number 646529405382

**Result** ✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Both

lower arm rear bushes. (2.4.G.2)

**Advice** Wipers poor.

**Advice** Items removed from driver's view prior to test Air Freshener.

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number
970051167381

Result
Advice
Both rear tyres worn on very inside edge.

Advice
Front Inner brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)

Advice
Undertray fitted.

Advice
Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check





Tax status	Expired at 29 February 2024
Days left	60 days too late
MOT expiry date	19 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

## Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
********	
*********	
************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIN
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-22
Last registration	2023-07-20
Complete history	See info



Registration #1	2013-05-22	19 mi
Registration #2	2016-05-05	37.495 mi
Registration #3	2017-04-27	49.641 mi
Registration #4	2018-04-25	58.498 mi
Registration #5	2018-06-27	59.386 mi
Registration #6	2019-06-22	61.568 mi
Registration #7	2020-12-15	86.264 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		0.00 44
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1581 kg
Max. allowed weight	2110 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	CFGC517648