



report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-18
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-25
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	12
Total items failed	23

MOT #19	2023-09-26 15:26
MOT test number	151079955767
Result	✓ Passed
Next expiry date	2024-09-25
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #18	2023-09-25 15:02
MOT test number	776055377685
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17	2022-08-30 12:14
MOT test number	245990380327
Result	✓ Passed

MOT #16	2022-08-30 12:14
MOT test number	928088040432
Result	✗ Failed
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #15**

2022-08-19 14:12

MOT test number

443217988938

Result**✗ Failed****Fail** Offside Front Obligatory mirror insecure (3.3 (b) (ii))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Offside Rear Brake pipe excessively corroded to flexi-hose (1.1.11 (c))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Offside Brake pipe excessively corroded central brake pipe (1.1.11 (c))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #14** 2021-08-24 14:36**MOT test number** 251146682926**Result** ✓ Passed**Advice** Slight underbody corrosion**MOT #13** 2020-08-17 13:45**MOT test number** 639743597023**Result** ✓ Passed**Advice** Underbody has general corrosion**MOT #12** 2020-08-14 13:59**MOT test number** 177190777369**Result** ✗ Failed**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Underbody has general corrosion**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2019-08-12 14:30**MOT test number** 621666354342**Result** ✓ Passed**MOT #10** 2018-08-14 14:18**MOT test number** 769983035952**Result** ✓ Passed**MOT #9** 2018-08-14 14:18**MOT test number** 637243071414**Result** ✗ Failed**Pass with rectification** Front Exhaust fumes causing a danger to health of persons on board (6.1.2 (b) (ii))

**MOT #8** 2017-08-14 14:27**MOT test number** 634479509234**Result** ✓ Passed**MOT #7** 2017-08-14 14:27**MOT test number** 361426999317**Result** ✗ Failed**Pass with rectification** Offside Front Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-08-12 14:28**MOT test number** 911635307034**Result** ✓ Passed**MOT #5** 2016-08-11 11:57**MOT test number** 249676286374**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Front Exhaust system not adequately supported (7.1.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #4 2015-09-02 11:44**MOT test number** 253771127052**Result** ✓ Passed**Advice** Sump has slight leak of oil



MOT #3	2014-08-19 09:30
MOT test number	385671434225
Result	✓ Passed
MOT #2	2013-08-12 10:57
MOT test number	969464523211
Result	✓ Passed
MOT #1	2012-08-17 09:50
MOT test number	689100732219
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	RO59EVR
Plate since	2019-09-29
Current registration	RO59EVR
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-11
Last registration	2023-09-26
Complete history	See info



Registration #1	2009-09-11	22 mi
Registration #2	2012-08-17	52.342 mi
Registration #3	2013-08-12	73.713 mi
Registration #4	2014-08-19	98.235 mi
Registration #5	2015-09-02	123.715 mi
Registration #6	2016-08-11	142.388 mi
Registration #7	2016-08-12	142.388 mi
Registration #8	2017-08-14	156.375 mi
Registration #9	2017-08-14	156.375 mi
Registration #10	2018-08-14	170.442 mi
Registration #11	2018-08-14	170.442 mi
Registration #12	2019-09-26	184.509 mi
Registration #13	2020-09-26	198.576 mi
Registration #14	2021-09-26	212.643 mi
Registration #15	2022-09-26	226.710 mi
Registration #16	2023-09-26	240.777 mi
Registration #17	2024-03-29	254.844 mi
Registration #18	2024-03-29	254.844 mi
Registration #19	2024-03-29	254.844 mi
Registration #20	2024-03-29	254.844 mi
Registration #21	2024-03-29	254.844 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9531732