



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI DESIRE PICASSO E4
Colour	Beige
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-05
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

**MOT #19** 2022-06-07 11:45**MOT test number** 900649104959**Result** ✗ Failed**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Central Upper Additional stop lamp not working. Disconnected?**Advice** Offside Front Tyre worn close to legal limit/worn on edge Low on both edges. 2mm. (5.2.3 (e))**MAJOR** Exhaust emissions exceed manufacturer's specified limit Plate limit 1.80m. Peak 8.06m. Average 4.44m. (8.2.2.2 (a))**Advice** Whirring noise noted during emission test accelerations.**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Slight 'chuffing' noise noted at idle behind engine cover. Suspect injector seal starting to fail. Recommend inspection and repair.**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Low on both edges. 2mm. 185/65R15 88H. (5.2.3 (e))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Outer Sill 'crunchy' under finger and thumb pressure but solid. Has had similar area repaired on nearside.**MOT #18** 2021-06-07 12:03**MOT test number** 117151931968**Result** ✓ Passed**MOT #17** 2020-09-01 08:36**MOT test number** 173604986169**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge BOTH FRONT (5.2.3 (e))

**MOT #16** 2020-09-01 08:36**MOT test number** 183227462566**Result** ✗ Failed**Pass with rectification** Exhaust system insecure Exhaust rear silencer mounting insecure (6.1.2 (a))**Advice** Tyre worn close to legal limit/worn on edge BOTH FRONT (5.2.3 (e))**MOT #15** 2019-08-12 08:09**MOT test number** 501569419769**Result** ✓ Passed**MOT #14** 2019-08-12 08:09**MOT test number** 671005365654**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13** 2018-08-07 07:41**MOT test number** 756300857485**Result** ✓ Passed**MOT #12** 2017-08-10 08:32**MOT test number** 334871166502**Result** ✓ Passed**MOT #11** 2016-08-12 09:13**MOT test number** 792252637250**Result** ✓ Passed**Advice** Rear exhaust corroding, has temporary bracket but still secure.

**MOT #10** 2015-08-11 14:46**MOT test number** 269841769929**Result** ✓ Passed**MOT #9** 2015-08-11 07:31**MOT test number** 327821227736**Result** ✗ Failed

- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Fail** Offside Rear Braking system leaking (3.6.A.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Rear rear brake recording little or no effort (3.7.B.5a)

**MOT #8** 2014-08-05 08:33**MOT test number** 646407114258**Result** ✓ Passed**MOT #7** 2013-08-13 13:01**MOT test number** 436435523274**Result** ✓ Passed

- Advice** Inner Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-08-12 09:26**MOT test number** 389324323209**Result** ✗ Failed

- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #5** 2012-08-03 08:35**MOT test number** 359756112447**Result** ✓ Passed**MOT #4** 2011-08-03 08:52**MOT test number** 349845011449**Result** ✓ Passed**Notice** Rear exhaust has temporary bracket, but is still secure.**MOT #3** 2010-08-20 08:52**MOT test number** 371392030426**Result** ✓ Passed**MOT #2** 2009-08-24 16:23**MOT test number** 600346739286**Result** ✓ Passed**Notice** Child Seats Fitted Not Allowing Full Inspection of Adult Seat Belts**MOT #1** 2009-08-24 13:07**MOT test number** 772696039212**Result** ✗ Failed**Notice** Child Seats Fitted Not Allowing Full Inspection of Adult Seat Belts**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-01
Last registration	2022-06-07
Complete history	<a href="#">See info</a>



Registration #1	2006-09-01	6 mi
Registration #2	2009-08-24	18.195 mi
Registration #3	2009-08-24	18.198 mi
Registration #4	2010-08-20	23.310 mi
Registration #5	2011-08-03	28.184 mi
Registration #6	2012-08-03	33.034 mi
Registration #7	2013-08-12	37.953 mi
Registration #8	2013-08-13	37.956 mi
Registration #9	2014-08-05	42.383 mi
Registration #10	2015-08-11	46.645 mi
Registration #11	2015-08-11	46.649 mi
Registration #12	2016-08-01	51.277 mi
Registration #13	2016-08-01	51.277 mi
Registration #14	2016-08-01	51.277 mi
Registration #15	2016-08-01	51.277 mi
Registration #16	2016-08-01	51.277 mi
Registration #17	2016-08-01	51.277 mi
Registration #18	2016-08-01	51.277 mi
Registration #19	2016-08-01	51.277 mi
Registration #20	2016-08-01	51.277 mi
Registration #21	2016-08-01	51.277 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB663111139