





report date: 2024-03-28

General information

Make	FIAT
Model	FULLBACK SX DCB
Colour	Blue
Year of manufacture	2017
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	379 Nm at 1.500 rpm
Engine capacity	2.442 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	46.3 mpg
Consumption combined	40.9 mpg
CO2 emission	180 g/km
CO2 label	1



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-03

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history	М	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-08-04	
MOT pass rate	57 %	
MOT passed	4	
Failed MOT tests	3	
Total advice items	10	
Total items failed	2	

MOT #7	2023-07-14 07:33
MOT test number	726146198044
Result	✓ Passed
Next expiry date	2024-08-04

MOT #6	2023-07-14 07:33
MOT test number	328232266015
Result	▼ Failed
Pass with rectification	Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))

MOT #5		2022-08-05 08:15
MOT test	number	842295427085
Result		✓ Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2022-07-18 12:43 871576869719 **MOT** test number Result × Failed **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Items removed from driver's view prior to test Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) **MAJOR Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #3
 2021-07-27 10:56

 MOT test number
 785885813083

 Result
 ✓ Passed

MOT #2

MOT test number

736278308534

Result

✓ Passed

MOT #1 2020-09-25 14:38

MOT test number 653559739000

Result × Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

CarCheck.co.uk page 4/11



SP67LVM report date: 2024-03-28





Tax status	Valid until 1 August
Days left	95
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
OWITCH	Thistory

Owner mistory	
For how long did the current and previous owner(s) have this FIAT? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	m.n.n
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-29
Last registration	2023-07-14
Complete history	See info



Registration #1	2017-09-29	9 mi
Registration #2	2020-09-25	44.199 mi
Registration #3	2020-09-25	44.199 mi
Registration #4		11.777 es
Registration #5	2021-07-27	49.604 mi
Registration #6		71.777 66
Registration #7		0.77 sc
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1785 mm
Height	1775 mm
Length	5285 mm
Kerb weight	1765 kg
Max. allowed weight	2800 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	UBC2479

CarCheck.co.uk page 11/11