



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-06
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-06-01
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #12	2021-06-02 16:52
MOT test number	177870981813
Result	✓ Passed
Next expiry date	2022-06-01

MOT #11	2020-08-05 13:52
MOT test number	229750438015
Result	✓ Passed

MOT #10	2019-09-16 09:37
MOT test number	140961483398
Result	✓ Passed

Advice Tyre worn close to legal limit/worn on edge both fronts and offside rear (5.2.3 (e))

MOT #9	2018-10-25 15:45
MOT test number	813172938802
Result	✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases flex (6.1.2 (a))

**MOT #8** 2018-10-24 09:26**MOT test number** 627219410734**Result** ✗ Failed**Fail** Offside Rear Position lamp not working upper (4.2.1 (a))**Fail** Windscreen washer not working (3.5 (a))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Exhaust has a minor leak of exhaust gases flex (6.1.2 (a))**MOT #7** 2017-10-25 12:44**MOT test number** 766149221721**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2016-11-01 13:02**MOT test number** 553978082966**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2015-11-03 14:59**MOT test number** 482019230375**Result** ✓ Passed

**MOT #4** 2015-11-03 14:08**MOT test number** 251021650901**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #3** 2014-11-11 13:37**MOT test number** 898745214312**Result** ✓ Passed**MOT #2** 2013-11-25 17:27**MOT test number** 899899523312**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2012-12-06 09:55**MOT test number** 925341842370**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✕
Untaxed

Tax expired:
1 June 2022

✕
MOT

Expired:
1 June 2022

Tax status	Expired at 1 June 2022
Days left	699 days too late
MOT expiry date	1 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BD59XJM
Plate since	2019-03-29
Current registration	BD59XJM
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-12-22
Last registration	2021-06-02
Complete history	See info



Registration #1	2009-12-22	13 mi
Registration #2	2012-12-06	61.781 mi
Registration #3	2013-11-25	73.422 mi
Registration #4	2014-11-11	86.046 mi
Registration #5	2015-11-03	102.094 mi
Registration #6	2015-11-03	102.094 mi
Registration #7	2016-11-01	119.991 mi
Registration #8	2016-11-01	119.991 mi
Registration #9	2016-11-01	119.991 mi
Registration #10	2016-11-01	119.991 mi
Registration #11	2016-11-01	119.991 mi
Registration #12	2016-11-01	119.991 mi
Registration #13	2016-11-01	119.991 mi
Registration #14	2016-11-01	119.991 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	591583
---------------	--------