





report date: 2024-03-29

General information

Make	MINI
Model	COOPER S
Colour	Blue
Year of manufacture	2012
Top speed	142 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2023-05-08

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

Date 2023-05-04

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-07
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #13		2024-04-05 12:34
MOT test	number	490971984209
Result		✓ Passed
Next expi	ry date	2025-04-07
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Under-trays fitted obscuring some underside components	
Advice	Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Advice	Covers fitted obscuring some components in the engine bay	

MOT #12	2023-03-29 09:38
MOT test number	517209437019
Result	✓ Passed

MOT #11	2022-03-31 07:30
MOT test number	870776594760
Result	✓ Passed
Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not serious (1.1.14 (a) (ii)) Advice Nearside Front Tyre slightly damaged/cracking or perishing on tread (

CarCheck.co.uk page 3/12



FH12RKY

report date: 2024-03-29

MOT #10 2022-03-29 12:20 **MOT test number** 512188993909 Result × Failed Fail Nearside Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii)) **Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened corroding (1.1.14 (a) (ii)) Bulb warning showing on instrument cluster but all lights working at time of test Advice **Advice** Nearside Front Tyre slightly damaged/cracking or perishing on tread (5.2.3 (d) (ii)) Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #9	2021-04-08 12:13
MOT test number	901514402851
Result	✓ Passed
MOT #8	2020-06-04 08:17
MOT test number	769211406743
Result	✓ Passed
MOT #7	2020-06-03 07:46
MOT test number	988041680859
Result	X Failed
Fail Nearside Front Service brake excessively binding (1.2.1 (f))	

MOT #6	2019-04-27 07:38
MOT test number	591657608881
Result	✓ Passed
MOT #5	2018-04-28 11:01
MOT test number	410685553630
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #4	2017-05-24 11:05
MOT test number	275659295637

MOT #3 2017-03-03 09:30

MOT test number 573007963062

Result Passed

Advice Outer sill covers and under trays fitted obscuring prescribed areas and components

MOT #2 2016-03-10 10:49

MOT test number 289132048436

Result

Passed

MOT #1 2015-07-02 09:03

MOT test number 128123385159

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE PARTY OF THE P	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	9
Current registration	NK NK
	UK
Plate since	
Current registration	ENIES GIES UK
	UK (
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$


CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-06-29
Last registration	2024-04-05
Complete history	See info



Registration #1	2012-06-29	25 mi
Registration #2	2015-07-02	16.496 mi
Registration #3	2016-03-10	19.692 mi
Registration #4	2017-03-03	23.724 mi
Registration #5	2017-05-24	23.937 mi
Registration #6	2018-04-28	26.604 mi
Registration #7	2019-04-27	30.047 mi
Registration #8	2020-06-03	32.723 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles2Engine numberA631J326