



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-16
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	9

MOT #13	2023-09-06 16:06
MOT test number	237975870550
Result	✓ Passed
Next expiry date	2024-09-23
Minor	Offside Front Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction scratched (3.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2023-09-06 08:41
MOT test number	600395534007
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Offside Front Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction scratched (3.1 (a) (i))
Fail	Nearside Rear Road wheel has a welding defect (5.2.2 (a))

**MOT #11** 2022-09-02 12:03**MOT test number** 764581637715**Result** ✓ Passed

- Advice** Offside Front Nail in tyre
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2021-09-24 08:39**MOT test number** 383102480126**Result** ✓ Passed**MOT #9** 2020-11-17 16:57**MOT test number** 335913140052**Result** ✓ Passed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2020-11-17 10:29**MOT test number** 454378426548**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2019-11-18 10:22**MOT test number** 644866822381**Result** ✓ Passed

- Advice** Under body and engine covers fitted

MOT #6 2018-12-17 10:10**MOT test number** 565387736257**Result** ✓ Passed

- Advice** Under body and engine covers fitted

MOT #5 2017-12-19 14:44**MOT test number** 251282312945**Result** ✓ Passed

- Advice** Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Rear Outer tyre sidewall has cut / tear



MOT #4	2017-08-30 06:46
MOT test number	964297571525
Result	✓ Passed
MOT #3	2017-03-23 13:25
MOT test number	944760207247
Result	✓ Passed
MOT #2	2017-03-23 11:52
MOT test number	989106422643
Result	✗ Failed
Fail	Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
MOT #1	2016-03-12 08:59
MOT test number	400761445254
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	23 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-30
Last registration	2023-09-06
Complete history	See info



Registration #1	2013-09-30	10 mi
Registration #2	2016-03-12	13.749 mi
Registration #3	2017-03-23	24.542 mi
Registration #4	2017-03-23	24.542 mi
Registration #5	2017-08-30	30.306 mi
Registration #6	2017-12-19	33.122 mi
Registration #7	2018-12-17	42.162 mi
Registration #8	2019-11-18	50.396 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi
Registration #15	2020-05-20	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CFHC520511