



General information

Make	MINI
Model	MINI (R57) COOPER
Colour	Red
Year of manufacture	2010
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 2



Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	8
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-02-15
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #15	2024-02-05 12:55
MOT test number	363345761549
Result	✓ Passed
Next expiry date	2025-02-15

MOT #14	2024-02-05 08:55
MOT test number	403865652760
Result	✗ Failed
Fail	Nearside Rear Upper Position lamp not working (4.2.1 (a) (ii))

MOT #13	2023-02-16 11:09
MOT test number	135390151129
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12	2022-02-09 09:42
MOT test number	612374734847
Result	✓ Passed

MOT #11	2021-02-12 11:28
MOT test number	760859464852
Result	✓ Passed

**MOT #10**

2020-08-28 12:13

MOT test number

368111177201

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9**

2020-08-27 09:13

MOT test number

894465564546

Result

✗ Failed

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Rear Upper Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8**

2019-09-07 08:33

MOT test number

437488722500

Result

✓ Passed

Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Items removed from driver's view prior to test**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing damage on inner sidewall, looks very close to exposing ply/cords (5.2.3 (d) (ii))



MOT #7	2018-08-15 10:58
---------------	------------------

MOT test number	236631350218
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2017-09-06 09:56
---------------	------------------

MOT test number	535584832443
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-08-17 13:54
---------------	------------------

MOT test number	823080456879
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-08-21 10:28
---------------	------------------

MOT test number	793981674765
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2014-09-10 08:47
---------------	------------------

MOT test number	379593554424
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-03-20 17:04
---------------	------------------

MOT test number	609429974057
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-04-11 11:57
---------------	------------------

MOT test number	799681503110
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-28
Last registration	2024-02-05
Complete history	See info



Registration #1	2010-06-28	20 mi
Registration #2	2013-04-11	23.566 mi
Registration #3	2014-03-20	32.472 mi
Registration #4	2014-09-10	36.489 mi
Registration #5	2015-08-21	40.161 mi
Registration #6	2016-08-17	43.396 mi
Registration #7	2017-09-06	47.392 mi
Registration #8	2018-08-15	51.591 mi
Registration #9	2019-09-07	54.172 mi
Registration #10	2020-09-07	56.377 mi
Registration #11	2021-09-07	58.582 mi
Registration #12	2022-09-07	60.787 mi
Registration #13	2023-09-07	62.992 mi
Registration #14	2024-02-05	65.197 mi
Registration #15	2024-02-05	67.402 mi
Registration #16	2024-02-05	69.607 mi
Registration #17	2024-02-05	71.812 mi
Registration #18	2024-02-05	74.017 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1165 kg
Max. allowed weight	1595 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number	B1771731
---------------	----------