



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVTI VX
Colour	Blue
Year of manufacture	2002
Top speed	105 mph
0 - 60 mph	11.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	126 BHP
Max. torque	177 Nm at 4.400 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-10
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	70 %
MOT passed	19
Failed MOT tests	8
Total advice items	57
Total items failed	26

MOT #27	2023-09-20 10:58
MOT test number	201144853255
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Age related corrosion underside of vehicle and some suspension components
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #26	2023-09-14 14:27
MOT test number	619676786556
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases Exhaust silencer pipe broken (6.1.2 (a))
Advice	Age related corrosion underside of vehicle and some suspension components
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #25	2022-08-19 14:21
MOT test number	371943867860
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security underbody corroded in places (6.2.2 (d) (i))
Minor	Front Headlamp lens slightly defective bothsides (4.1.1 (b) (i))

**MOT #24**

2022-08-19 14:21

MOT test number

453673269557

Result**✗ Failed****Minor** Front Headlamp lens slightly defective bothsides (4.1.1 (b) (i))**Advice** Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security underbody corroded in places (6.2.2 (d) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #23**

2021-09-16 12:29

MOT test number

853574165642

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #22**

2021-09-16 12:14

MOT test number

768540447799

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail

Offside Headlamp light intensity severely reduced (4.1.4 (a))

Advice

Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail

Nearside Headlamp light intensity severely reduced (4.1.4 (a))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #21

2020-09-23 11:28

MOT test number

585424592686

Result**✓ Passed****Advice**

Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view scratched in centre (3.2 (a) (i))

Advice

Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

Advice

Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #20**

2020-09-18 13:58

MOT test number

283373528326

Result**✗ Failed**

- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Fail** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view scratched in centre (3.2 (a) (i))
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Fail** Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))

MOT #19

2019-08-23 14:03

MOT test number

202026987831

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm and cracking (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm and cracking (5.2.3 (e))



MOT #18	2019-08-23 10:46
MOT test number	521425593084
Result	✗ Failed
Fail	Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm and cracking (5.2.3 (e))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm and cracking (5.2.3 (e))
Fail	Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #17	2018-09-05 14:46
MOT test number	988710132559
Result	✓ Passed
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Vehicles internal headlight adjuster altered to recheck lights

**MOT #16**

2018-09-05 09:04

MOT test number

896484449082

Result**✗ Failed****Minor**

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Vehicles internal headlight adjuster altered to recheck lights

Fail

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #15

2017-09-14 10:02

MOT test number

809007830357

Result**✓ Passed****Advice**

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Vehicle structure has slight corrosion (6.1.A.1)

Advice

Both rear tyres cracking

Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

**MOT #14** 2016-09-06 10:45**MOT test number** 523446516341**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Both rear tyres cracking**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Vehicle structure has slight corrosion (6.1.A.1)**Advice** Both front tyres cracking**MOT #13** 2015-09-08 10:23**MOT test number** 855382494213**Result** ✓ Passed**MOT #12** 2014-08-29 10:50**MOT test number** 818271644250**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #11** 2014-08-29 10:50**MOT test number** 526571844226**Result** ✗ Failed**Pass with rectification** Centre Rear Stop lamp not working (1.2.1b)**Notice** Items removed from driver's view prior to test**MOT #10** 2013-08-30 13:00**MOT test number** 537112343261**Result** ✓ Passed

**MOT #9** 2012-09-07 08:14**MOT test number** 725201252255**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2011-09-10 12:05**MOT test number** 355933351210**Result** ✓ Passed**MOT #7** 2010-09-17 15:18**MOT test number** 383560660289**Result** ✓ Passed**Notice** Brake pads wearing low**Notice** Front tyre treads wearing close to legal limits, craks in treads**MOT #6** 2010-09-15 11:34**MOT test number** 952278450200**Result** ✗ Failed**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Notice** Brake pads wearing low**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Notice** Front tyre treads wearing close to legal limits, craks in treads**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**MOT #5** 2009-09-03 15:29**MOT test number** 992556049216**Result** ✓ Passed



MOT #4	2008-09-04 17:20
MOT test number	341348048429
Result	✓ Passed
MOT #3	2007-09-06 17:41
MOT test number	970019547217
Result	✓ Passed
MOT #2	2006-08-24 10:42
MOT test number	692166536264
Result	✓ Passed
MOT #1	2005-09-13 11:20
MOT test number	282116355272
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
9 March 2024

✓

MOT

Expires:
19 September 2024

Tax status	Expired at 9 March 2024
Days left	50 days too late
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	MC52ZRF
Plate since	2024-03-28
Current registration	MC52ZRF
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-09-18
Last registration	2023-09-20
Complete history	See info



Registration #1	2002-09-18	6 mi
Registration #2	2005-09-13	12.511 mi
Registration #3	2006-08-24	14.992 mi
Registration #4	2007-09-06	18.378 mi
Registration #5	2008-09-04	20.300 mi
Registration #6	2009-09-03	22.746 mi
Registration #7	2010-09-15	26.141 mi
Registration #8	2010-09-17	26.156 mi
Registration #9	2011-09-10	31.823 mi
Registration #10	2012-09-07	36.564 mi
Registration #11	2013-08-30	41.443 mi
Registration #12	2014-08-29	44.936 mi
Registration #13	2015-09-08	47.973 mi
Registration #14	2016-09-06	52.593 mi
Registration #15	2016-09-06	52.593 mi
Registration #16	2016-09-06	52.593 mi
Registration #17	2016-09-06	52.593 mi
Registration #18	2016-09-06	52.593 mi
Registration #19	2016-09-06	52.593 mi
Registration #20	2016-09-06	52.593 mi
Registration #21	2016-09-06	52.593 mi
Registration #22	2016-09-06	52.593 mi
Registration #23	2016-09-06	52.593 mi
Registration #24	2016-09-06	52.593 mi
Registration #25	2016-09-06	52.593 mi
Registration #26	2016-09-06	52.593 mi

Registration #27	2025-25-25	25,252,252
Registration #28	2025-25-25	25,252,252

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1660 mm
Length	4115 mm
Kerb weight	1150 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ4326115