



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G



**MOT history**

MOT expiry date	2024-02-29
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	27
Total items failed	9

MOT #16	2023-03-01 15:25
MOT test number	166586840325
Result	✓ Passed
Next expiry date	2024-02-29
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2021-10-25 15:31
MOT test number	541427968329
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread damaged and cracked (0.1 (b))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #14**

2021-10-25 10:37

MOT test number

894642340330

Result

✗ Failed

Advice Front Registration plate deteriorated but not likely to be misread damaged and cracked (0.1 (b))**Advice** Nearside Front Nail in tyre x2**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205-50-17 (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**MOT #13**

2020-09-05 08:15

MOT test number

413787782553

Result

✓ Passed

MOT #12

2019-09-02 15:34

MOT test number

757424194988

Result

✓ Passed

Advice Offside front tyre worn to limits on inside edges**MOT #11**

2019-09-02 07:29

MOT test number

238161606669

Result

✗ Failed

Advice Offside front tyre worn to limits on inside edges**Fail** Offside Front Road wheel badly distorted (5.2.2 (c) (i))



MOT #10	2018-09-03 07:41
MOT test number	311843042208
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2018-09-03 07:41
MOT test number	100091640443
Result	✗ Failed
Pass with rectification	Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

MOT #8	2017-09-05 10:35
MOT test number	933640804605
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit Inner edge (4.1.E.1)

MOT #7	2017-09-01 16:07
MOT test number	527667574591
Result	✗ Failed
Fail	Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Front Tyre worn close to the legal limit Inner edge (4.1.E.1)
Fail	Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Fail	Front position lamp(s) incorrect colour (1.1.A.3e)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #6	2016-09-03 09:56
---------------	------------------

MOT test number	661202870736
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-08-29 10:32
---------------	------------------

MOT test number	688507319692
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear has a nail in tyre
---------------	----------------------------------

MOT #4	2015-08-29 09:46
---------------	------------------

MOT test number	145001925977
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
-------------	--

Advice	Nearside Rear has a nail in tyre
---------------	----------------------------------

MOT #3	2014-09-03 12:51
---------------	------------------

MOT test number	829656844239
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-08-31 11:59
---------------	------------------

MOT test number	145343843250
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-09-03 12:15
---------------	------------------

MOT test number	428407842285
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✗
MOT

Expired:
29 February 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	29 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	GK59WNV
Plate since	2019-03-28
Current registration	GK59WNV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-03
Last registration	2023-03-01
Complete history	See info



Registration #1	2009-09-03	9 mi
Registration #2	2012-09-03	20.546 mi
Registration #3	2013-08-31	28.600 mi
Registration #4	2014-09-03	35.674 mi
Registration #5	2015-08-29	41.323 mi
Registration #6	2015-08-29	41.323 mi
Registration #7	2016-09-03	49.334 mi
Registration #8	2017-09-01	61.766 mi
Registration #9	2017-09-05	61.856 mi
Registration #10	2019-09-03	75.377 mi
Registration #11	2019-09-03	75.377 mi
Registration #12	2019-09-03	75.377 mi
Registration #13	2019-09-03	75.377 mi
Registration #14	2019-09-03	75.377 mi
Registration #15	2019-09-03	75.377 mi
Registration #16	2019-09-03	75.377 mi
Registration #17	2019-09-03	75.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607