



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | BEETLE LUNA 8V |
| Colour | Silver |
| Year of manufacture | 2006 |
| Top speed | 111 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 102 BHP |
| Max. torque | 148 Nm at 3.800 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.7 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 36.2 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-24 |
| Pictures | 22 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-21 |
| MOT pass rate | 84 % |
| MOT passed | 16 |
| Failed MOT tests | 3 |
| Total advice items | 30 |
| Total items failed | 5 |

| | |
|------------------|----------------------------------------------------------------------|
| MOT #19 | 2023-12-22 14:22 |
| MOT test number | 359319548311 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-21 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---------------------------------------------------------------------------------------------------------------------------|
| MOT #18 | 2022-11-28 13:14 |
| MOT test number | 144303703223 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) |
| Advice | Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement n/s & o/s (5.3.4 (a) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Minor | Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt n/s & o/s (2.1.3 (g) (i)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

**MOT #17**

2022-11-28 13:02

MOT test number

343961681122

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))**Minor** Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt n/s & o/s (2.1.3 (g) (i))**Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement n/s & o/s (5.3.4 (a) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #16**

2021-11-15 07:12

MOT test number

622096880340

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2021-04-26 11:46

MOT test number

271892259553

Result

✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14** 2021-04-26 11:46**MOT test number** 843073925582**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**MOT #13** 2020-04-18 12:20**MOT test number** 714642570620**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin x2 (1.1.13 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge x2 (5.2.3 (e))**MOT #12** 2019-05-01 15:06**MOT test number** 993422419029**Result** ✓ Passed**MOT #11** 2018-05-09 12:10**MOT test number** 566137784799**Result** ✓ Passed**MOT #10** 2017-05-02 08:23**MOT test number** 340979873806**Result** ✓ Passed

**MOT #9** 2016-05-05 09:43**MOT test number** 996229238903**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-04-08 11:51**MOT test number** 925198395012**Result** ✓ Passed**MOT #7** 2014-03-31 13:42**MOT test number** 405090894010**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-03-31 13:42**MOT test number** 809410794051**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2013-04-10 14:59**MOT test number** 475470103155**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



| | |
|-----------------|---------------------------------------------------------|
| MOT #4 | 2012-04-10 13:37 |
| MOT test number | 405961002146 |
| Result | ✓ Passed |
| Advice | Nearside Inner Front Brake pad(s) wearing thin (3.5.1g) |
| Advice | Offside Inner Front Brake pad(s) wearing thin (3.5.1g) |

| | |
|-----------------|------------------|
| MOT #3 | 2011-02-01 17:44 |
| MOT test number | 899762531077 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #2 | 2010-03-02 12:48 |
| MOT test number | 790591860029 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2009-09-03 12:44 |
| MOT test number | 872106249230 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
21 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 21 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|-----------------------------------------------------------------------------------------------|
| Number of plates | 1 |
| Current registration |  EX56CWN |
| Plate since | 2019-06-29 |
| Current registration |  EX56CWN |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2006-09-01 |
| Last registration | 2023-12-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-09-01 | 23 mi |
| Registration #2 | 2009-09-03 | 17.884 mi |
| Registration #3 | 2010-03-02 | 19.791 mi |
| Registration #4 | 2011-02-01 | 19.964 mi |
| Registration #5 | 2012-04-10 | 22.712 mi |
| Registration #6 | 2013-04-10 | 25.211 mi |
| Registration #7 | 2014-03-31 | 32.001 mi |
| Registration #8 | 2015-04-08 | 35.815 mi |
| Registration #9 | 2016-05-05 | 35.907 mi |
| Registration #10 | 2017-05-02 | 36.294 mi |
| Registration #11 | 2018-05-02 | 36.294 mi |
| Registration #12 | 2019-05-02 | 36.294 mi |
| Registration #13 | 2020-05-02 | 36.294 mi |
| Registration #14 | 2021-05-02 | 36.294 mi |
| Registration #15 | 2022-05-02 | 36.294 mi |
| Registration #16 | 2023-05-02 | 36.294 mi |
| Registration #17 | 2024-05-02 | 36.294 mi |
| Registration #18 | 2025-05-02 | 36.294 mi |
| Registration #19 | 2026-05-02 | 36.294 mi |
| Registration #20 | 2027-05-02 | 36.294 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1724 mm |
| Height | 1502 mm |
| Length | 4081 mm |
| Wheel base | 2516 mm |
| Kerb weight | 1393 kg |
| Max. allowed weight | 1770 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | BFS 047594 |