



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	LAGUNA EXPRESSION DCI (100BHP)
Colour	Black
Year of manufacture	-
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	200 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	9
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #25	2021-09-01 13:37
MOT test number	456603558996
Result	✓ Passed
Next expiry date	2022-09-30

MOT #24	2020-10-01 10:56
MOT test number	523381470113
Result	✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #23	2020-09-30 09:40
MOT test number	312649424865
Result	✗ Failed

- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #22**

2019-09-26 15:52

MOT test number

121090306976

Result

✓ Passed

- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn on outer edge
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Tyre worn on outer edge close to ply/cords

MOT #21

2019-09-23 09:29

MOT test number

985716715920

Result

✗ Failed

- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn on outer edge
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn on outer edge close to ply/cords

**MOT #20**

2018-10-01 12:07

MOT test number

242104324884

Result

✓ Passed

Advice Nearside Play in steering rack inner joint(s)**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #19**

2018-09-25 14:51

MOT test number

759123348415

Result

✗ Failed

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Play in steering rack inner joint(s)**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #18**

2017-09-27 10:27

MOT test number

537973142896

Result

✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front steering rack misting oil**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)

**MOT #17** 2017-09-27 10:27**MOT test number** 495259833097**Result** ✗ Failed**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Advice** Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front steering rack misting oil**MOT #16** 2016-09-26 10:18**MOT test number** 694762542526**Result** ✓ Passed**Advice** Offside Front steering rack misting oil**Advice** Nearside Front adult seat belt not checked due to child seat**Advice** Nearside Front worn on inner edge**MOT #15** 2015-09-21 09:24**MOT test number** 670011968958**Result** ✓ Passed**Advice** Play in inner rack joints.**Advice** Covers under bonnet and underside.

**MOT #14** 2014-09-26 08:30**MOT test number** 259439264233**Result** ✓ Passed**Notice** Rear exhaust rubbers perished.**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Oil leak**MOT #13** 2014-09-25 12:31**MOT test number** 345978164245**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Notice** Oil leak**Notice** Rear exhaust rubbers perished.**MOT #12** 2013-09-27 11:19**MOT test number** 689950873207**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/r tyre worn on outer edge

**MOT #11** 2013-09-24 14:21**MOT test number** 816627863256**Result** ✗ Failed**Fail** Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Nail in offside rear tyre**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** O/s/r tyre worn on outer edge**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #10** 2012-09-29 11:45**MOT test number** 326783772483**Result** ✓ Passed

**MOT #9** 2012-09-28 10:59**MOT test number** 238422772274**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** The car is unroadworthy and just needs to be carefully driven to repair centre**Fail** Centre Rear Stop lamp not working (1.2.1b)**Fail** Offside Front coil spring fractured (2.4.C.1a)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**MOT #8** 2011-09-27 12:06**MOT test number** 275090471201**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2010-09-20 12:28**MOT test number** 823803960254**Result** ✓ Passed**MOT #6** 2010-09-20 09:14**MOT test number** 730083360240**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

**MOT #5** 2009-09-05 15:09**MOT test number** 382168849421**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2009-09-05 13:08**MOT test number** 441038449230**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #3** 2008-08-27 09:29**MOT test number** 872370748291**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-08-21 09:57**MOT test number** 330384838235**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)



MOT #1	2007-06-27 10:40
MOT test number	141398977175
Result	✓ Passed
Advice	Offside Track rod end ball joint has slight play (2.2.B.1f)
Notice	Slightly high handbrake lever travel



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	LW04EKA
Plate since	2019-03-28
Current registration	LW04EKA
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 MONTHS
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2004-07-26
Last registration	2021-09-01
Complete history	See info



Registration #1	2004-07-26	24 mi
Registration #2	2007-06-27	38.327 mi
Registration #3	2008-08-21	57.746 mi
Registration #4	2008-08-27	57.765 mi
Registration #5	2009-09-05	63.330 mi
Registration #6	2009-09-05	63.330 mi
Registration #7	2010-09-20	66.895 mi
Registration #8	2010-09-20	66.896 mi
Registration #9	2011-09-27	69.040 mi
Registration #10	2012-09-28	72.481 mi
Registration #11	2012-09-29	72.483 mi
Registration #12	2013-09-24	78.178 mi
Registration #13	2013-09-27	78.193 mi
Registration #14	2014-09-25	82.871 mi
Registration #15	2015-09-29	85.337 mi
Registration #16	2016-09-29	85.337 mi
Registration #17	2017-09-29	85.337 mi
Registration #18	2018-09-29	85.337 mi
Registration #19	2019-09-29	85.337 mi
Registration #20	2020-09-29	85.337 mi
Registration #21	2021-09-29	85.337 mi
Registration #22	2022-09-29	85.337 mi
Registration #23	2023-09-29	85.337 mi
Registration #24	2024-09-29	85.337 mi
Registration #25	2025-09-29	85.337 mi
Registration #26	2026-09-29	85.337 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1752 mm
Height	1422 mm
Length	4572 mm
Wheel base	2743 mm
Kerb weight	1315 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	C040314