





report date: 2024-03-29

General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Black
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-05-24

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2023-03-18
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	46
Total items failed	3

MOT #17	2023-04	l-28 14:11
MOT test	number 6529	89086452
Result		X Failed
MAJOR (5.3.4 (a) (Nearside Front Lower Suspension arm ball joint excessively worn ball joint worn and cover (i))	rsplit
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
MAJOR	Nearside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread slightly deteriorated (0.1	(b))

MOT #16	2022-03-19 10:17
MOT test number	492423708335
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



MOT #15 2022-03-17 12:21

MOT test number 500036614993

Result X Failed

DANGEROUS Nearside Rear Anti-roll bar missing (5.3.3 (a) (ii))

MAJOR Offside Rear fog lamp lens defective such that emitted light is adversely affected (4.5.1 (b) (ii))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #14 2021-03-09 14:38

MOT test number 478658586603

Result / Passed

Advice O/s/r tyre low on inside tread

Advice Suspension arm pin or bush worn but not resulting in excessive movement both fronts (5.3.4 (a)

(i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

Advice N/s/r tyre bald on inside tread

Advice Brake pad(s) wearing thin both fronts (1.1.13 (a) (ii))

CarCheck.co.uk page 4/15



Advice

O/s/r tyre low on inside tread

WV10PJO

report date: 2024-03-29

MOT #13 2021-03-09 09:28 **MOT** test number 164646215432 Result **★** Failed **MAJOR** Windscreen wiper does not clear the windscreen effectively both fronts (3.4 (b) (ii)) Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii)) Advice Advice N/s/r tyre bald on inside tread Advice Suspension arm pin or bush worn but not resulting in excessive movement both fronts (5.3.4 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Brake pad(s) wearing thin both fronts (1.1.13 (a) (ii)) Advice Advice Offside Front Nail in tyre

MOT #12		2020-03-18 13:29
MOT test	number	337651522594
Result		✓ Passed
Advice	Brake pad(s) wearing thin BOTH FRONTS (1.1.13 (a) (ii))	
Advice	Offside Rear Nail in tyre	
Advice	BOTH REAR TYRES LOW ON INSIDE + CUPPING	
Advice (a) (i))	Suspension arm pin or bush worn but not resulting in excessive movement	BOTH FRONTS (5.3.4
Advice	Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT	S (1.1.14 (a) (ii))
Advice	O/S/F TYRE LOW ON TREAD	

CarCheck.co.uk page 5/15



MOT #11

Advice

Advice

Advice

Advice

(a) (i))

O/S/F TYRE LOW ON TREAD

Offside Rear Nail in tyre

WV10PJO report date: 2024-03-29

2020-03-18 10:38

Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONTS (1.1.14 (a) (ii))

Suspension arm pin or bush worn but not resulting in excessive movement BOTH FRONTS (5.3.4

MOT #10

MOT test number

907921059655

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #9

2018-03-10 10:52

MOT test number

259831473958

Result

✓ Passed

MOT #8

2018-03-10 10:52

MOT test number

188289916293

Result

✓ Pass with rectification

Offside Rear Registration plate lamp insecure (1.1.C.1c)

CarCheck.co.uk page 6/15



MOT #7		2017-03-04 09:51
MOT test number		664297325781
Result		✓ Passed
MOT #6		2017-03-04 09:51
MOT test number		785959532636
Result		★ Failed
Pass with rectification	Nearside Front Headlamp aim too high (1.8)	

MOT #5		2016-03-19 15:11
MOT test	number	169568100310
Result		✓ Passed
MOT #4		2015-03-07 13:53
MOT test	number	919306265070
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2014-03-14 11:29
MOT test number	896333574044
Result	✓ Passed
MOT #2	2013-03-08 09:00
MOT test number	735307763069
Result	✓ Passed

CarCheck.co.uk page 7/15



MOT #1 2013-03-08 09:00

MOT test number 865447863003

Result X Failed

Pass with rectification

Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

CarCheck.co.uk page 8/15



Tax & MOT check

Tax expired: 28 April 2023



X MOT

Expired: 18 March 2023

Tax status	Expired at 28 April 2023
Days left	366 days too late
MOT expiry date	18 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-18
Last registration	2023-04-28
Complete history	See info



Registration #1	2010-03-18	9 mi
Registration #2	2013-03-08	23.225 mi
Registration #3	2014-03-14	32.225 mi
Registration #4	2015-03-07	42.610 mi
Registration #5	2016-03-19	53.148 mi
Registration #6	2017-03-04	62.785 mi
Registration #7	2017-03-04	62.785 mi
Registration #8	2018-03-10	73.254 mi
Registration #9	2018-03-10	73.254 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number AS14346