





report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Grey
Year of manufacture	2009
Top speed	111 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-12-16

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-09
------	------------


Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-06
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	16
Total items failed	8

MOT #17	2023-05-30 07:35
MOT test number	151198731231
Result	✓ Passed
Next expiry date	2024-06-06

MOT #:	16	2023-05-25 08:35
MOT te	st number	569184232310
Result		× Failed
Fail	Nearside Headlamp levelling device inoperative (4.1.5 (a))	
Fail	Offside Rear Brake pipe excessively corroded part of front to back pipe (1.1.11 (c))	
Fail	Nearside Rear Brake pipe excessively corroded part of front to back pipe (1.1.11 (c))

MOT #15	2	022-06-07 12:12
MOT test	number	804772263218
Result		✓ Passed
Advice	Brake hose slightly deteriorated both rear (1.1.12 (b) (ii))	
Advice	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))	
Advice	Brake pipe corroded, covered in grease or other material both front to rear (1.1.11	(c))

CarCheck.co.uk page 3/13



EK09CTZ

report date: 2024-03-29

MOT #14 2021-09-09 11:55

MOT test number 911028682595

Result
✓ Passed

MOT #13 2020-09-11 11:37

MOT test number 509258004973

Result ✓ Passed

MOT #12 2020-09-11 11:37

MOT test number 210387434923

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #11 2019-09-11 10:26

MOT test number 711404837247

Result \rightarrow Passed

Advice Both front tyres worn on edges

Fail

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10 2018-09-06 10:56

MOT test number 711961226911

MOT #9 2018-09-05 15:27

MOT test number 215079232454

Result X Failed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/13



MOT #8 2017-09-05 13:24

MOT test number 126313342474

MOT #7 2017-09-01 14:41

MOT test number 783354727125

Result × Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Rear parking brake recording little or no effort (3.7.B.6a)

MOT #6 2016-08-11 09:58

MOT test number 962405268615

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Both front tyres worn heavily on edges close to limit

Advice Nearside Rear Nail in tyre

MOT #5 2015-09-04 14:51

MOT test number 171076941514

Result

Passed

Advice Offside Front brake binding slightly

Advice Nearside Rear nail in tyre

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



MOT #4 2015-09-04 14:51

MOT test number 968850976169

Result × Failed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear nail in tyre

Pass with rectification Offside Headlamp aim beam image obviously incorrect bulb incorrectly fitted

(1.8.A.1b)

Advice Offside Front brake binding slightly

MOT #3 2014-09-04 13:48

MOT test number 847347844201

Result ✓ Passed

MOT #2 2014-03-11 15:35

MOT test number 915120574046

Result
✓ Passed

MOT #1 2012-08-13 15:30

MOT test number 256516422283

Result
✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo here.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-04-17
Last registration	2023-05-30
Complete history	See info



Registration #1	2009-04-17	6 mi
Registration #2	2012-08-13	32.362 mi
Registration #3	2014-03-11	44.435 mi
Registration #4	2014-09-04	46.563 mi
Registration #5	2015-09-04	58.651 mi
Registration #6	2015-09-04	58.651 mi
Registration #7	2016-08-11	66.077 mi
Registration #8	2017-09-01	73.764 mi
Registration #9	2017-09-05	73.804 mi
Registration #10	2018-09-05	81.231 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		0.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****

Video <u>see crash video</u>



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030522228

CarCheck.co.uk page 13/13