





report date: 2024-03-29

General information

Make	BMW
Model	116 116D SPORT
Colour	Red
Year of manufacture	2015
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-16
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	16
Total items failed	10

MOT #11		2023-11-30 12:08
MOT test	number	939757509819
Result		✓ Passed
Next expi	ry date	2024-12-16
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Under-trays fitted	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2023-11-30 10:59
MOT test number	458999410157
Result	★ Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Under-trays fitted	

CarCheck.co.uk page 3/12



MOT #9 2022-12-17 13:50

MOT test number 143403501207

Advice Trays and covers fitted

MOT #8 2022-12-15 18:25

MOT test number 165901936666

Result × Failed

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Trays and covers fitted

MOT #7 2021-12-14 11:53

MOT test number 463921306673

Result

Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2021-12-01 07:27

MOT test number 682418536784

Result × Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Front Exhaust system insecure (6.1.2 (a))

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #5 2020-10-02 15:17

MOT test number 103452313857

Result ✓ Passed

CarCheck.co.uk page 4/12



Pass with rectification

Result

MJ65XZA report date: 2024-03-29

X Failed

MOT #4 2019-10-09 10:08

MOT test number 598543947653

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-10-09 10:08

MOT test number 773982821012

Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-10-14 12:16

MOT test number 132902939477

Result ✓ Passed

MOT #1 2018-10-08 10:47

MOT test number 864285952160

Result X Failed

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	16 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	hictory
Owner	HISLOFY

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>has</u>		?
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		

	More info >	
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	UK NEW	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-21
Last registration	2023-11-30
Complete history	See info



Registration #1	2015-09-21	13 mi
Registration #2	2018-10-08	27.792 mi
Registration #3	2018-10-14	27.792 mi
Registration #4	2019-10-09	35.889 mi
Registration #5	2019-10-09	35.889 mi
Registration #6	2020-10-02	39.590 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		70.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number35229309