



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VTR PLUS EGS GRAND PICASSO
Colour	Blue
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-03-14
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	24
Total items failed	4

MOT #15	2023-03-15 12:24
MOT test number	613735416138
Result	✓ Passed
Next expiry date	2024-03-14

MOT #14	2023-03-13 17:12
MOT test number	205483822316
Result	✗ Failed
DANGEROUS Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))	
MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2021-09-21 14:09
MOT test number	667110126437
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt all rear

**MOT #12**

2021-09-20 13:36

MOT test number

678280798243

Result**✗ Failed****Advice** Child Seat fitted not allowing full inspection of adult belt all rear**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip missing (6.1.7 (g) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**DANGEROUS** Tyre has a tear, caused by separation or partial failure of its structure both rear 225/60x16 (5.2.3 (d) (ii))**MOT #11**

2020-09-28 10:34

MOT test number

822230136951

Result**✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10**

2019-09-23 08:39

MOT test number

414870877550

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2018-10-01 07:56

MOT test number

709088137586

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2017-09-28 08:39**MOT test number** 469857486636**Result** ✓ Passed**MOT #7** 2016-09-30 09:19**MOT test number** 546710677410**Result** ✓ Passed

- Advice** Under trays fitted
- Advice** Offside Front Tyre worn close to the legal limit inner edge secondary tread (4.1.E.1)
- Advice** Engine covers fitted
- Advice** Nearside Front Tyre worn close to the legal limit outer edge secondary tread (4.1.E.1)

MOT #6 2016-09-30 09:19**MOT test number** 622288307668**Result** ✗ Failed

- Advice** Under trays fitted
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Advice** Offside Front Tyre worn close to the legal limit inner edge secondary tread (4.1.E.1)
- Advice** Engine covers fitted
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Tyre worn close to the legal limit outer edge secondary tread (4.1.E.1)

MOT #5 2015-10-02 15:33**MOT test number** 938475940430**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2014-09-01 16:09
MOT test number	848944344264
Result	✓ Passed
MOT #3	2013-09-06 12:27
MOT test number	256969543270
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
MOT #2	2012-08-30 16:56
MOT test number	687113242237
Result	✓ Passed
MOT #1	2011-08-25 15:38
MOT test number	409647631220
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-01
Last registration	2023-03-15
Complete history	See info



Registration #1	2008-09-01	6 mi
Registration #2	2011-08-25	15.729 mi
Registration #3	2012-08-30	22.164 mi
Registration #4	2013-09-06	27.876 mi
Registration #5	2014-09-01	36.000 mi
Registration #6	2015-10-02	45.382 mi
Registration #7	2016-09-30	51.100 mi
Registration #8	2016-09-30	51.100 mi
Registration #9	2017-09-28	55.939 mi
Registration #10	2018-09-28	59.377 mi
Registration #11	2019-09-28	62.815 mi
Registration #12	2020-09-28	66.253 mi
Registration #13	2021-09-28	69.691 mi
Registration #14	2022-09-28	73.129 mi
Registration #15	2023-03-15	76.567 mi
Registration #16	2023-03-15	76.567 mi
Registration #17	2023-03-15	76.567 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1539 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBAJ3070542