



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI SE NAV BLUE DRIVE
Colour	Silver
Year of manufacture	2015
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.700 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C









Internet history

Entry 2




Date	2021-10-23
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-08-12
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-05
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #7	2023-07-28 15:33
MOT test number	788576493348
Result	✓ Passed
Next expiry date	2024-08-05

MOT #6	2022-08-02 14:34
MOT test number	299097997050
Result	✓ Passed

MOT #5	2021-08-06 15:08
MOT test number	163832723133
Result	✓ Passed

MOT #4	2020-09-07 14:55
MOT test number	118528447561
Result	✓ Passed

**MOT #3** 2019-09-02 13:28**MOT test number** 502251470453**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective smeary (3.4 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**MOT #2** 2018-07-04 15:43**MOT test number** 560029387774**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #1** 2018-07-04 14:32**MOT test number** 469750201040**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
5 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-29
Last registration	2023-07-28
Complete history	See info



Registration #1	2015-06-29	12 mi
Registration #2	2018-07-04	32.273 mi
Registration #3	2018-07-04	32.273 mi
Registration #4	2019-09-02	48.020 mi
Registration #5	2020-09-07	58.612 mi
Registration #6	2020-09-07	58.612 mi
Registration #7	2020-09-07	58.612 mi
Registration #8	2020-09-07	58.612 mi
Registration #9	2020-09-07	58.612 mi
Registration #10	2020-09-07	58.612 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4745 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDFU507229