





report date: 2024-03-29

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Silver
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	260 g/km
CO2 label	M



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 2


Date 2021-10-11

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-09
Pictures	26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT expiry date	2023-03-25
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	30
Total items failed	20

MOT #18		2022-03-26 14:20
MOT test n	umber	297892683459
Result		✓ Passed
Next expir	y date	2023-03-25
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))		
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #17	2021-03-22 17:37
MOT test number	126851761032
Result	✓ Passed
Advice Linkages and ball joints worn and rusted below car	

MOT #16	2021-03-19 13:21
MOT test number	655281654886
Result	× Failed
Fail Offside Front Suspension arm has an unsafe modification (5.3.3 (c) (i)) Advice Linkages and ball joints worn and rusted below car	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #15 2021-03-04 10:42

MOT test number 437866218485

Result X Failed

Advice Front Brake hose slightly deteriorated both side o/s and n/s (1.1.12 (b) (ii))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Front Direction indicator not working (4.4.1 (a) (ii))

Advice Nearside Front fog lamp not working

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2020-03-12 18:39

MOT test number 935779603979

MOT #13 2020-03-12 14:23

MOT test number 420276123212

Result X Failed

Fail Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #12 2019-02-26 18:12

MOT test number 617939692163

Result ✓ Passed

Advice Nearside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11 2018-03-12 18:24

MOT test number 666791251748

Result

Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2018-02-28 17:34

MOT test number 769494332962

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2017-02-27 17:02

MOT test number 406386828944

Result
✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-29

2017-02-23 13:14 **MOT #8 MOT test number** 681761238204 Result × Failed Fail Nearside Front Wheel bolt(s) missing (4.2.A.1e) Fail Nearside Rear Wheel bolt(s) missing (4.2.A.1e) Fail Nearside Front Lower Gas suspension unit fouled by moving parts likely to cause damage (2.4.D.1c) Fail Nearside Steering rack gaiter insecure (2.2.D.2d) Offside Front Wheel bolt(s) missing (4.2.A.1e) Fail Fail Offside Rear Wheel bolt(s) missing (4.2.A.1e) Nearside Front Lower Gas suspension unit fouled by moving parts likely to restrict travel (2.4.D.1c) Fail

MOT #7		2015-09-22 11:35
MOT test	number	350185508672
Result		✓ Passed
Advice lower rear	Offside Front Suspension arm rubber bush deteriorated but not resulting in bush (2.4.G.2)	excessive movement
Advice	Nearside Front Brake pipe slightly corroded pipe on brake calliper (3.6.B.2c))
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)	
Advice	Nearside Front Brake pipe slightly corroded pipe on calliper (3.6.B.2c)	

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #6 2015-09-22 07:18 **MOT** test number 297414540499 Result × Failed Fail Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower rear bush (2.4.G.2) Advice Nearside Front Brake pipe slightly corroded pipe on brake calliper (3.6.B.2c) Advice Offside Front Seat belt stitching slightly frayed (5.2.2b) Advice Nearside Front Brake pipe slightly corroded pipe on calliper (3.6.B.2c)

MOT test number

S57586174266

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-09-30 14:38 **MOT** test number 446203674275 Result × Failed **Advice** Front Brake pad(s) wearing thin (3.5.1g) Notice Child seat fitted not allowing full inspection of adult belt **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d) Notice O/S/F daytime running lamp not working **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #3	2013-09-10 13:25
MOT test number	327993253274
Result	✓ Passed
Notice Items removed from driver's view prior to test	

MOT #2	2012-09-17 12:16
MOT test number	607761162208
Result	√ Passed
MOT #1	2011-09-02 12:28
MOT test number	418145741225
Result	✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check

Tax expired: 1 March 2022



X MOT

Expired: 25 March 2023

Tax status	Expired at 1 March 2022
Days left	791 days too late
MOT expiry date	25 March 2023
Full MOT history	See MOT history

Tax calculation

Waltisla slave	40
Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

e when miscory		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
THE PARTY OF THE P		

THE STREET STREE		
	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-18
Last registration	2022-03-26
Complete history	See info



Registration #1	2008-09-18	9 mi
Registration #2	2011-09-02	37.846 mi
Registration #3	2012-09-17	53.474 mi
Registration #4	2013-09-10	67.423 mi
Registration #5	2014-09-30	84.092 mi
Registration #6	2014-10-03	84.092 mi
Registration #7	2015-09-22	98.998 mi
Registration #8	2015-09-22	98.998 mi
Registration #9	2017-02-23	107.293 mi
Registration #10	2017-02-27	107.294 mi
Registration #11	2018-02-28	124.512 mi
Registration #12		71.777 es
Registration #13		11.700 mg
Registration #14		71.777 es
Registration #15		11.700 mi
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15

Number of axles 2

Engine number CAS 025689