





report date: 2024-03-28

General information

Make	MINI
Model	CLUBMAN COOPER D
Colour	Grey
Year of manufacture	2018
Top speed	132 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	2.8 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-10-17

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-10-17
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

, -		
Date	2021-10-16	
Pictures	15	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/11



FV18NNR

report date: 2024-03-28

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2025-02-14
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #6	2024-02-15 15:42
MOT test number	428181473084
Result	✓ Passed
Next expiry date	2025-02-14

MOT #5	2024-02-15 11:12
MOT test number	243224526402
Result	X Failed
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #4	2023-06-01 12:53
MOT test number	978015167365
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



MOT #3 2023-05-31 13:25

MOT test number 992323434955

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Front Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #2 2022-05-30 10:10

MOT test number 447514755332

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2021-05-21 15:06

MOT test number 367822263436

Result \(\sqrt{Passed} \)

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



FV18NNR

report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union mestery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-05-31
Last registration	2024-02-15
Complete history	See info



Registration #1	2018-05-31	13 mi
Registration #2	2021-05-21	23.578 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es

More info >

CarCheck.co.uk page 10/11



FV18NNR

report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	68%
Pedestrian	68%
Safety systems	67%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1395 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles 2

Engine number 58625326