



General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	White
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-27
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-10-15
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	32
Total items failed	5

**MOT #10**

2023-08-18 10:14

MOT test number

613265532461

Result**✗ Failed**

- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- MAJOR** Rear Exhaust has a major leak of exhaust gases back box missing (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- MAJOR** Offside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))
- DANGEROUS** Undertray likely to become detached (6.2.1 (a) (ii))
- Advice** Offside Front Brake pipe slightly damaged (1.1.11 (c))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #9

2021-10-16 10:30

MOT test number

415707178219

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #8** 2020-10-08 12:22**MOT test number** 728240271591**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-04-02 11:46**MOT test number** 304772751365**Result** ✓ Passed**MOT #6** 2018-03-17 13:19**MOT test number** 415744094653**Result** ✓ Passed**MOT #5** 2017-03-24 12:49**MOT test number** 124109482904**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2016-04-02 10:52**MOT test number** 399669018124**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit 235/65/r17 (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2016-04-02 09:50**MOT test number** 827077976807**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit 235/65/r17 (4.1.E.1)**Fail** Rear Upper Stop lamp not working (1.2.1b)**Advice** Inner wheel arch cover loose**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2015-04-09 10:38**MOT test number** 999419695090**Result** ✓ Passed**MOT #1** 2015-04-07 11:10**MOT test number** 225997195072**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2022

✕
MOT

Expired:
15 October 2022

Tax status	Expired at 1 September
Days left	606 days too late
MOT expiry date	15 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-22
Last registration	2023-08-18
Complete history	See info



Registration #1	2012-06-22	12 mi
Registration #2	2015-04-07	38.168 mi
Registration #3	2015-04-09	38.171 mi
Registration #4	2016-04-02	47.984 mi
Registration #5	2016-04-02	47.984 mi
Registration #6	2017-03-24	55.520 mi
Registration #7	2019-05-29	55.557 mi
Registration #8	2019-05-29	55.557 mi
Registration #9	2019-05-29	55.557 mi
Registration #10	2019-05-29	55.557 mi
Registration #11	2019-05-29	55.557 mi
Registration #12	2019-05-29	55.557 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172829K