



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2023-03-13
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

Entry 1

Date	2022-01-04
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #21</b>	2023-05-18 15:52
<b>MOT test number</b>	948614410887
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-05-17
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Surface corrosion under vehicle

<b>MOT #20</b>	2023-05-18 14:16
<b>MOT test number</b>	572999934955
<b>Result</b>	✗ Failed
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Surface corrosion under vehicle
<b>Fail</b>	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

<b>MOT #19</b>	2022-12-08 18:02
<b>MOT test number</b>	670809413734
<b>Result</b>	✓ Passed
<b>Advice</b>	General rust under the car
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #18</b>	2022-12-08 15:27
<b>MOT test number</b>	122621759195
<b>Result</b>	✗ Failed
<b>Advice</b>	General rust under the car
<b>Fail</b>	Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Brake disc worn, but not excessively all around (1.1.14 (a) (i))
<b>Fail</b>	Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))



**MOT #17** 2021-12-10 14:17**MOT test number** 610318819300**Result** ✓ Passed**MOT #16** 2021-12-07 14:14**MOT test number** 205003067946**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Holes in axle (O/S and N/S) (5.3.6 (a) (i))**MOT #15** 2020-11-26 11:44**MOT test number** 424861620319**Result** ✓ Passed**MOT #14** 2020-11-25 08:56**MOT test number** 566025179111**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13** 2019-10-31 09:51**MOT test number** 171480549726**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12**

2019-10-30 13:17

**MOT test number**

255014752988

**Result**

✗ Failed

**Fail** Offside Front Brake pipe excessively corroded to rear at rear (1.1.11 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Nearside Front Brake pipe excessively corroded to rear at rear (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #11**

2018-11-13 10:57

**MOT test number**

960030376442

**Result**

✓ Passed

**Advice** PARKING BRAKE LEVER TRAVEL**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10**

2017-11-18 10:53

**MOT test number**

375688796816

**Result**

✓ Passed

**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9**

2016-11-23 15:21

**MOT test number**

146405543824

**Result**

✓ Passed

**MOT #8** 2016-11-16 14:19**MOT test number** 434045896933**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not fitted (1.1.C.1b)**Fail** Front front brake binding both (3.7.B.1)**MOT #7** 2015-12-12 10:22**MOT test number** 424369985756**Result** ✓ Passed**MOT #6** 2014-12-22 11:24**MOT test number** 278006554391**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-12-30 11:45**MOT test number** 436964163336**Result** ✓ Passed**MOT #4** 2013-07-30 10:49**MOT test number** 367181113292**Result** ✓ Passed**MOT #3** 2012-07-21 09:57**MOT test number** 545933702244**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-07-16 10:54
MOT test number	425997991146
Result	✓ Passed
Notice	Added 1.5 ltrs off oil
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Advise near side rear brake disc corroded and pitted
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1	2010-07-29 12:04
MOT test number	630310710227
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-07-30
Last registration	2023-05-18
Complete history	<a href="#">See info</a>



Registration #1	2007-07-30	29 mi
Registration #2	2010-07-29	35.902 mi
Registration #3	2011-07-16	40.983 mi
Registration #4	2012-07-21	49.161 mi
Registration #5	2013-07-30	58.785 mi
Registration #6	2013-12-30	60.990 mi
Registration #7	2014-12-22	66.933 mi
Registration #8	2015-12-12	71.650 mi
Registration #9	2016-11-16	76.761 mi
Registration #10	2016-11-23	76.838 mi
Registration #11	2017-11-18	80.535 mi
Registration #12	2018-11-13	84.880 mi
Registration #13	2019-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi
Registration #15	2019-05-20	85.277 mi
Registration #16	2019-05-20	85.277 mi
Registration #17	2019-05-20	85.277 mi
Registration #18	2019-05-20	85.277 mi
Registration #19	2019-05-20	85.277 mi
Registration #20	2019-05-20	85.277 mi
Registration #21	2019-05-20	85.277 mi
Registration #22	2019-05-20	85.277 mi
Registration #23	2019-05-20	85.277 mi
Registration #24	2019-05-20	85.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6749744