



report date: 2024-03-29

## General information

Make	VOLVO
Model	XC70 XC70 D5 AWD SE LUX EU4
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-04-02
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-03-03
<b>MOT pass rate</b>	82 %
<b>MOT passed</b>	14
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	24
<b>Total items failed</b>	5

<b>MOT #17</b>	2024-03-04 16:15
<b>MOT test number</b>	157694235208
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-03-03

<b>MOT #16</b>	2023-02-28 16:20
<b>MOT test number</b>	459999559554
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2022-03-04 13:36
<b>MOT test number</b>	622676158692
<b>Result</b>	✓ Passed

- Advice** Poss leak fuel filter
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge and worn inner edge (5.2.3 (e))

**MOT #14** 2022-02-18 09:19**MOT test number** 582733587714**Result** ✗ Failed**Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Poss leak fuel filter**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge and worn inner edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2020-05-12 15:28**MOT test number** 270252199977**Result** ✓ Passed**MOT #12** 2019-05-10 15:08**MOT test number** 447767021002**Result** ✓ Passed**MOT #11** 2018-10-30 14:52**MOT test number** 825937985293**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2018-10-30 10:24

**MOT test number**

595330365717

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9**

2017-11-07 11:27

**MOT test number**

821368056966

**Result****✓ Passed****MOT #8**

2016-07-19 12:54

**MOT test number**

487360100795

**Result****✓ Passed****Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** OSR and NSR springs corroded.**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Outer parking bulb out.**MOT #7**

2015-07-20 12:37

**MOT test number**

327911805471

**Result****✓ Passed****Notice** Wipers smearing.**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2014-07-24 16:28**MOT test number** 585415704294**Result** ✓ Passed**MOT #5** 2013-07-15 16:38**MOT test number** 799066093193**Result** ✓ Passed**MOT #4** 2012-07-30 14:42**MOT test number** 217872912292**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-09-01 09:28**MOT test number** 309914241405**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-08-30 11:45**MOT test number** 338842641414**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Direction indicators missing (1.4.A.2b)**MOT #1** 2010-08-31 12:04**MOT test number** 232273540220**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
3 March 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	3 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-03
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2007-09-03	8 mi
Registration #2	2010-08-31	38.110 mi
Registration #3	2011-08-30	50.889 mi
Registration #4	2011-09-01	51.007 mi
Registration #5	2012-07-30	60.589 mi
Registration #6	2013-07-15	68.276 mi
Registration #7	2014-07-24	76.788 mi
Registration #8	2015-07-20	81.924 mi
Registration #9	2016-07-19	86.341 mi
Registration #10	2017-11-07	87.916 mi
Registration #11	2018-05-20	91.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2020-05-20	99.377 mi
Registration #14	2021-05-20	103.377 mi
Registration #15	2022-05-20	107.377 mi
Registration #16	2023-05-20	111.377 mi
Registration #17	2024-03-04	115.377 mi
Registration #18		
Registration #19		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2100 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1877 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	572691