






report date: 2024-03-28

General information

| Make | FIAT |
|---------------------|-------------------|
| Model | 500C POP DUALOGIC |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 99 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 69 BHP |
|-------------------------|---------------------|
| Max. torque | 102 Nm at 6.000 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 113 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



RF11UGN report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-29

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-03-13 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 10 |
| Total items failed | 5 |

| MOT #15 | 2024-03-14 16:03 |
|--|------------------|
| MOT test number | 989227747982 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-13 |
| Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e | <u>=</u>)) |
| Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view Cracked. (3.2 (a) (i)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

| MOT #14 | 2023-03-13 15:47 |
|---|---|
| MOT test | number 633213980283 |
| Result | ✓ Passed |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| MOT #13 | 2022-02-17 09:24 |
|-----------------|------------------|
| MOT test number | 640794564746 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



Advice

RF11UGN

report date: 2024-03-28

MOT #12

MOT test number

Result

Pass with rectification

Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #11

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

MOT test number

724549611665

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #9 2020-04-02 07:33 **MOT** test number 460273405153 Result ✓ Passed 2019-05-03 09:06 **MOT #8 MOT test number** 214114618206 Result Passed **MOT #7** 2018-05-10 14:03 **MOT** test number 992957417038 Result ✓ Passed

CarCheck.co.uk page 4/12

Offside Front Shock absorber has a light misting of oil (2.7.3)



report date: 2024-03-28

MOT #6 2017-05-17 14:20

MOT test number 763568594713

MOT #5 2016-04-05 08:03

MOT test number 169658711912

Result ✓ Passed

MOT #4 2016-04-05 08:03

MOT test number 956021610518

Result X Failed

Pass with rectification Registration plate lamp not working (1.1.C.1d)

MOT #3 2015-04-04 11:14

MOT test number 685494495000

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2014-04-11 16:46

MOT test number 987331104161

MOT #1 2014-04-11 15:58

MOT test number 418201504126

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 337 |
| MOT expiry date | 13 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

| _ | |
|-------|---------|
| Owner | history |
| OWILL | 1113601 |

| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
|---|-------------|
| | |
| HARMAN AND AND AND AND AND AND AND AND AND A | |
| | |
| ************************************** | |
| | |
| ********* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



RF11UGN report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

 $\quad \text{More info} \quad > \quad$


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2011-04-13 |
| Last registration | 2024-03-14 |
| Complete history | See info |



| Registration #1 | 2011-04-13 | 28 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-04-11 | 27.360 mi |
| Registration #3 | 2014-04-11 | 27.362 mi |
| Registration #4 | 2015-04-04 | 37.174 mi |
| Registration #5 | 2016-04-05 | 49.198 mi |
| Registration #6 | 2016-04-05 | 49.198 mi |
| Registration #7 | 2017-05-17 | 54.530 mi |
| Registration #8 | 2018-05-10 | 60.629 mi |
| Registration #9 | 2019-05-03 | 63.259 mi |
| Registration #10 | | 71.777 es |
| Registration #11 | | 71.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1627 mm |
|---------------------|---------|
| Height | 1488 mm |
| Length | 3546 mm |
| Wheel base | 2300 mm |
| Kerb weight | 865 kg |
| Max. allowed weight | 1305 kg |

Additional information

| Fuel tank capacity | 35 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 12/12 |

Number of axles2Engine number6491843