





report date: 2024-03-29

General information

Make	ТОУОТА
Model	PROACE L2H1 HDI 1200 P/V
Colour	White
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-06


Pictures 37

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



EA63XOD report date: 2024-03-29

MOT history

MOT expiry date	2023-02-07
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	12
Total items failed	10

MOT #9	2022-02-08 12:48
MOT test number	825923609745
Result	✓ Passed
Next expiry date	2023-02-07
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #8	2022-02-08 12:48
MOT test number	281906811523
Result	× Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Pass with rectification Front Windscreen washer provides insufficient washer liqu	uid (3.5 (a))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2020-11-27 10:46

MOT test number 381865595996

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #6 2019-12-05 17:11

MOT test number 183492747210

Result ✓ Passed

Advice Engine very noisy

MOT #5 2019-12-05 14:13

MOT test number 190920033449

Result X Failed

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Windscreen washer not working (3.5 (a))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Engine very noisy

Fail Offside Windscreen washer not working (3.5 (a))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2018-11-29 14:07
MOT test r	number	774223140796
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2017-12-05 12:27
MOT test number	551244920460
Result	✓ Passed
MOT #2	2016-12-01 13:14
MOT test number	884897469126
Result	✓ Passed
MOT #1	2016-12-01 10:02
MOT test number	038047747658

MOI #1	2016-12-01 10:02
MOT test number	938047747658
Result	X Failed
Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 5/12



EA63XOD report date: 2024-03-29

Tax & MOT check



Tax expired: 1 September 2022

X MOT

Expired: 7 February 2023

Tax status	Expired at 1 September
Days left	605 days too late
MOT expiry date	7 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



EA63XOD report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-12-12
Last registration	2022-02-08
Complete history	See info



Registration #1	2013-12-12	20 mi
Registration #2	2016-12-01	79.911 mi
Registration #3	2016-12-01	79.911 mi
Registration #4	2017-12-05	111.337 mi
Registration #5	2018-11-29	128.484 mi
Registration #6	2019-12-05	138.458 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	RH04059395

CarCheck.co.uk page 12/12